Blackfoot/Lloyd

Husky Energy

Tank Inspection Report


Location: 100/10-24	1-49-	3 W4M	Tank Type: Tax	nk 1 Prod.	Date: Nov. 14, 2018
Mfg: WillO INDUST		Year blt:			3 CAP: 1000 bbl
Floor Thk: 14"		Shell Thk: 14"	3/164	Roof Thk:	3/16"
Requisitioned by: Mike	Ross	A	pprover: <u>Dee</u>	Nelson	Approver Code: 2Z-200425
wo#: 50061964	PO#: <u> </u>	8401226309	_ cc:	SAP	# : 66155561

ID	Item	Yes	Good	N/A	See Notes
	GENERAL				Notoc
T1	Other (Please Explain)				
T2	Corrosion			V	
T3	Leaks	1		1	
T4	Vibration	+		V	
T5	Dissimilar Flange Rating	+		1/	
T6	Ladder/Stairway	1	1/1		
T7	Platform	1/	1/		
T8	Electrical Ground	1	1/		
T9	Cathodic Protection	Ť	V	1/	
T10	Painted Inactive Corrosion	-		1	
T11	Coating/Painting	+		1	
T12	Level Gauge	1	V	V	
T13	Bottom	1./	V	_	1
T14	Secondary Containment	17/	V		
T15	Shell	1	V		
T16	Roof	1V	1/		
T17	Agitator/ Mixer	V	-	-	
	SUPPORTS			V	
T31	Other (Please Explain)				
T32	Foundation	1	V		1
T33	Anchor Bolts	-	V	1	'
T34	Windgirders	-		./	
134	CONNECTIONS			V	
T41	Other (Please explain)				
T42	Small Branches		/		
T43	Nozzles	~	V,		
T44	Pipe Manifolds	~	V.	/	
T45	Swing Lines	+		Y /	
T46		+	/	V	
T47	Manways/Hatches Reinforcing Pads	V	<i>V/</i>		
		1V	V	/	
T48	Inadequate Thread Engagement		/	V	
T49	Bolting	V	V		
T50 T51	Flanges	V	V	/	
101	Leak Clamps			V	
TC4	INSULATION				
T61	Other (Please explain)	-/			~
T62	Damage Penetrations	IV,	_/		0
T63 T64	Jacket	/	V	/	
T65		-		V/	
T66	Banding Seals/Joints	-		*/	
100	RELIEF DEVICE			V	
T7+					
T7t	Other (Please explain)	-			
T72	Corrosion				
T73 T74	Leaks Restricted InleUOutlet				
	IRESPUCIED INTELLIGITATION				

INTERNAL INSPECTION

ID	Item	Yes	Good	N/A	See Notes
	GENERAL				
T1	Other (Please Explain)			,	
T2	Corrosion			V	
T3	Erosion			V,	
T4	Distortion			V	
T5	Blisters			V	
T6	Deposits			V	
T7	Welds	V	V		
T8	Nozzles		V		
T9	Shell	V	1		
T10	Roof	V	1		
T11	Floor	V			
	GENERAL	1	,		
T21	Other - Firetube		V		3
T21	Other - Anodes			\checkmark	
T22	Annular Ring		(4	V	
T23	Sump			V	
T24	Roof Supports		,		
T25	Thermowells			,	
T26	Metallic Linings			V	
T27	Non Metallic Linings	1	,	V	
T28	Internal Steam Coil / other Piping	V	V		
T29	Level Gauge	V	V		
T30	Other Welded Attachements	V	/	/	
Bacl	welding Req'd			V	

ID	Notes
1	Tank on clarks
2	Tank on planks Areas Slightly Bubbled
3	Sout noted in Firetube, appears to be straight.
	be Straight.
	3 1 111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	18/
	Ψ
\vdash	
\vdash	
\vdash	
 	77



^{8&}quot; and 4" nozzle and repads were Magnetic particle inspected (MT), and the nozzles were backwelded and MT carried out.



NONDESTRUCTIVE INSPECTION REPORT

CA1213-NDT-39

Page 1 of 1

Type of Inspection: VT/UT

Rev: 3.0

Test Technique: UT thickness Equipment: DMSGO, FH2E, Flashlight, Grinder

Code/Standard: Client Information

Client: HUSKY OIL OPERATIONS LIMITED

IRISNDT #: LYN1801819


Location: 100/10-24-049-03w4

Item Inspected: Tank #1 production

Date: 14-Nov-18 WO #: 50061964 PO#: 8401226309

Appr# 2Z-2000425

A UT and Visual inspection was carried out on the following 1000BBL oil tank for the purpose of continued fitness for service and determination of inspection interval. See the field report for results of inspection, UT recorded values and inspection interval.





Recommendations:

No recommendations

Tank suitable for service

Note: Spot UT carried out on the floor and shell as a representation of overall integrity not a 100% scan method. DMSGO # 31139 cal. date due. June 1 2019 Probe: FH2E SN: SCA0620

nspection Limitation(s):	Only 1st course cleaned for inspection
--------------------------	--

Consumables: Interpretation by: Kilometers: Logan Skinner SNT-TC-1A: _____ Out: ___ Hrs: (Print) 1 Requested By: Mike Ross Out: Hrs: Approver: Dee Nelson C.G.S.B #: 17159 (Sign) Personnel: Client Representative: Logan Skinner (Print) I am in full agreement with report contents

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873 Calgary (403) 279-6121 Cold Lake

Lloydminster (780) 875-6455 (780) 674-3018 Barrhead Nisku (780) 955-7616

Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com

Engineering, Calgary Engineering, Edmonton Rope Access Services

Offices also located in USA and UK

(Sign)

(403) 217-9684 (780) 437-2022 (780) 437-2022

IRISNDT-CA-E-2015F 14-Nov-2018 13:07