

**VESSEL (A): 0483171** DATE OF INSPECTION: 2002 Feb 22



Ea# 6617 2348

## **Certificate of Inspection**

**EXXON MOBIL CANADA** 

237-4 AVENUE SW ATTN KEN MILLAR CALGARY, AB T2P 3M9

PREFERRED RE-INSP. INTERVAL: 2.00 Yr.

YEAR BUILT: 2002

CRN: P8150.2

SERIAL #: 7751-03

**LOCATION: LSD 6-22-57-20 W5M** 

**DESCRIPTION:** HORIZONTAL SEPARATOR (D-11)

MANUFACTURER: NATCO CANADA

**COMPANY CODE:** 

**VOLUME: 8.028 M3** 

**HEATING SURFACE:** 

**SURFACE AREA:** 

Safety Valves

MAX. AUTHORIZED MAX. TEMP MIN. TEMP VALVE ID **SETTING** CAPACITY LOCATION **PART** 

**WORKING PRESSURE** 

VESSEL

10204 KPA

38 C

-29 C

SV1

TO BE INSTALLED

## **OWNER INSTRUCTIONS/REMARKS:**

CONTACT THE ABSA SAFETY CODES OFFICER BEFORE PLACING THE VESSEL/BOILER IN SERVICE.

VESSEL/BOILER TO BE INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT AND REGULATIONS.

VERIFY THAT VESSEL/BOILER IS PROTECTED BY AN ACCEPTABLE ASME CODE PRESSURE RELIEF VALVE, OF ADEQUATE CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED AND INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT & REGULATIONS.

> MAR 18 Mobil Oil Canada General Accounting

Safety Codes Officer: LEE, SAI-BONG

Signature:

NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.