

MAGNETIC PARTICLE INSPECTION REPORT

CA1098-MT3-109

Page 1 of 2

Procedure: 5.0 Technique: MT-2V

Other:

Rev: 3.0

Client: HUSKY OIL OPERATIONS

Date: 2019-Sep-17 WO #: 81425700

Code/Standard: Crack detection

IRISNDT #: LYN1901541 Location: 6-34-42-1W4M

Item Inspected: 250BBL Tank s/n# 08-053-2

PO #: 8401358779

Specification: Standard:			
Surface Condition: Buffed	Material: Carbon Steel	Thickness: >3/16"	Heat Treatment: Not Applicable
Magnetizing Equipment: Yoke	Method of Magnetization: AC Continuous	Asset #: 40130	Mfg: contour probe
Verification Date: 2019-Sep-17	Verification Weight: ⊠ 10 lb. ☐ 40 lb.	Asset #: 49045	Verification per ASME V Art 7 T-762
Magnetic Particles: Dry ☐ Wet ⊠	Red 🗌 Grey 🗌 Black 🛛	Fluorescent	
Batch #: 65072518	Manufacture: ARDROX		Type: 8032
⊠Background			
Batch #: 65041718	Manufacture: ARDROX		Type: 8901W
☐Blacklight (N/A)			
Asset #:	Blacklight	meter: Asset #:	Cal Due Date:
⊠Whitelight			
Lighting Equipment: Yoke Light (10W)	Verification per ASME V Art 7 T-	777.1	
Inspection Scope: wet black MPI on tank lifting lugs			
a wet black magnetic particle inspection was carried out as requested on two existing lifting lug welds. welds were inspected for cracks or other relevant linear indications. RESULTS: no relevant linear indications present.	No.	API SEZI ED. SERIAL NO. SEZI ED. OWNER TAG NO. NISKU, AB. BATTLEFORD, S. OM DIA SEZIONES S. S. OM HT.	CAMROSE, AB.
Inspection Limitation(s): n/a			
Uni#: Out: Hrs: In: Out: Hrs: Personnel: STEPHEN BRYAN / BRADY HARVEY	Consumables: MIN REQUESTED BY Kristy Leeson APPROVER: CLAYTON CAMBELL 2Z-02013123	I am in full agreement with report contents	yan SNT-TC-1A: II (Level) C.G.S.B.#: 12459 int) gn)
5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873			

(780) 826-6105

(780) 743-1536

(403) 347-1742

www.irisndt.com

Cold Lake

Red Deer

Fort McMurray

(403) 279-6121

(780) 875-6455

(780) 674-3018

(780) 955-7616

Calgary

Barrhead

Lloydminster

(403) 217-9684

(780) 437-2022

(780) 437-2022

Engineering, Calgary

Engineering, Edmonton

Rope Access Services


Offices also located in USA and UK




MAGNETIC PARTICLE INSPECTION REPORT

CA1098-MT3-109

Page 2 of 2



Lifting lug 1



Lifting Lug 2

IRISNDT #: LYN1901541

Client: HUSKY OIL OPERATIONS

Date: 2019-Sep-17

(Print)

Stephen Bryan

(Sign)

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873 Calgary (403) 279-6121 Cold Lake

Lloydminster Barrhead

Nisku

(780) 875-6455 (780) 674-3018 (780) 955-7616 Fax (780) 436-48 Cold Lake Fort McMurray Red Deer (780) 826-6105 (780) 743-1536 (403) 347-1742 www.irisndt.com Engineering, Calgary (403 Engineering, Edmonton (780 Rope Access Services (780 Offices also located in USA and UK

(403) 217-9684 (780) 437-2022 (780) 437-2022