

MANUFACTURER'S DATA REPORT For Indirect Fired Heater Coils

General Safety Services Division Boilers Branch 3/26549 (A) No. 3/2/542

	•			
anufactured by	ARGO SALE	S LTD.		
anufactured for				
ltimate Owner _	DOMINION E	XPLORERS		
	•			
ocation of Inst			1005	
fg. Serial No.	L 239	Year Bui		
rawing Number	DM033B	····	Intended Service <u>HEAT 1</u>	NATURAL GAS
Material Sp	ecifications	SA106B	A105 RTJWN Sch. 160	1500#
		COLL	Ends (Flanges/N.P.T. A105 RFWN Sch. 80	
. Material Sp	acifications	Coil	Ends (Flanges/N.P.T.	
	2"	t Mhirkmann	0.344" 0/A Length	12' C/A 0.0625"
. Diameter . Diameter		om. Thickness	0.344" O/A Length	12' c/A 0.0625"
		23276	bbe at Maximum Temperat	ure 93 •6
. Maximum Wor . Maximum Wor	king Pressur	9310	kPa at Maximum Temperat	ura <u>93 </u>
olumo			kPa C.R.N. M4212.2 iography 40% (Rando F.W.H.	r. <u>No</u>
design, materi	.el, constructed Design No.	ents in this retion, and works M4212.2	eport are correct and that manship of this coil bund! The port are correct and that coil bund! For ARG	
		CERTIFICATE	OF SHOP INSPECTION	
Alberta Labou and state to with the Boil	r, General Sa the best of m ers and Press	authorized Bo fety Services y knowledge an ure Vessels Ac	iler and Pressure Vessel Division have inspected t d belief, the construction t and Regulations.	IIO TACLE HISTORY AND
Date (<u></u>	ovened free	Burgan	
			J. R. Suls	CB~47 (89/Ó