


Controller



Conclusion

All three bays, and the Controller passed the inspections and load tests with no immediate concerns regarding the long-term operation or reliability of the system. That said it is imperative that these systems receive the suggested maintenance at the suggested intervals to ensure proper operation and uptime.