

Location	# of Joints	Length (m)	Diameter (mm)	Wall Thickness (mm)	Spec
Jackfish Lake Boneyard	27	387	323.9	7.9	448
Jackfish Lake Boneyard	10	186	114.3	4.8	359
Jackfish Lake Boneyard	6	113.28	273.1	6.4	359
Jackfish Lake Boneyard	16	300	168.3	4.8	359
Jackfish Lake Boneyard	10	190	219.1	5.6	359
Jackfish Lake Boneyard	3	54	273.1	9.8	359
Jackfish Lake Boneyard	45	796.5	323.9	7.1	386
Jackfish Lake Boneyard	13	238	273.1	6.4	359
Jackfish Lake Boneyard	26	480	406.4	8.7	448
Jackfish Lake Boneyard	27	500	273.1	6.4	359
Jackfish Lake Boneyard	11	205	323.9	9.5	359
Jackfish Lake Boneyard	28	721	323.9	9.5	359
Jackfish Lake Boneyard	31	585	273.1	6.4	359
Jackfish Lake Boneyard	38	703	273.1	6.4	359
Jackfish Lake Boneyard	17	310	323.9	9.5	359
Jackfish Lake Boneyard	25	470	219.1	5.6	359
Jackfish Lake Boneyard	4	74	168.3	4,8	359

Mill	Coating	Year of coating
Evrax	Ultrabond III 14 mil	2017
Evrax	YJ2K	2022
Evrax	Shaw YJ	2019
Evrax	Shaw YJ	unknown
Evrax	Shaw YJ	2019
Evrax	Brown Fusion Bond	2021
Evrax	Shaw YJ	2021
Evrax	Shaw YJ	2022
Evrax	Ultrabond III 14 mil	2019
Evrax	Ultrabond III 14 mil	2019
Nexsteel Korea	ultrabond III 40 mil	2024
Evrax	Shaw YJ	2024
Evrax	Shaw YJ	2024
Evrax	Shaw YJ	2024
Nexsteel Korea	Ultrabond III 40 mil	2024
Evrax	Ultrabond III 40 Mil	couldn't read
Borusan Mannesmann Turkey	Ultrabond III 40 Mil	couldn't read

Conditions and Comments	Project Allocation
-------------------------	--------------------

Good

Good