



Zama Area Based Closure
Vessels & Tanks Checklist

Equipment Location DLS: 07 - 34 - 114 - 06 w6

Equipment Type: Vessel Tank Buried Tank Other: _____

Description: Free water k.o FG scrubber

Tag Number: _____

Serial Number: 2902 - 25H

A Number (Vessels): _____

- Disconnect piping
- Inhibit hazardous fluids / neutralize corrosive substances if necessary.
- Drain and suck out fluids.
- Remove solid, sludge, sediment, deposits.
- Clean interior (by steam if necessary). Open vents before steaming.
- Consider removal of internals (filters, traps, strainers, exchangers).
- Purge and dry interior, using air or nitrogen, until equipment is as dry as possible.
- Leave open to atmosphere, prevent entry by people or animals. e.g. open small vent, install non-pressure containing plug, blind with split gasket or standoffs, etc.
- Nameplate to remain attached.
- Equipment to remain at current location.
- Attach tag to equipment stating: 'Out of Service'. If tank is buried, erect above ground sign stating: 'Buried Tank - Out of Service'.
- Complete field transfer. Info required for field transfer: DLS Location, Vessel or tank serial number, Vessel A number, Photo of Vessel/tank name plate.

Comments: _____

Fieldwork completed by: Percoffe, Portmore

Checklist completed by: Ron Knuttila or Todd Larson

Ver 7, 2019-04-15
Prepared by: Joe Catalano, Matt France, Kim Scott.
Reviewed by: Dave Larsen, John Hawkins, Olga Kosteckýj

This summary adapted from:
Paramount PRESSURE EQUIPMENT INVENTORY MANAGEMENT PROCEDURE 4.4-PRD-014PEIM Rev. 5