



Field Inspection Report - Keyera Inc. # 372

VesselNumber: A0094591 **Vessel Name:** LPG Bullet **Province:** Alberta
District: Simonette/Plant **LSD:** LSD 9-6-63-25 W **Location:** SIMONETTE
Inspect Date: 9/15/2013 **Inspection Interval:** 60 **Next Inspection:** 9/15/2018
CRN: B4279.2 **Skid Number:** V-2-18A **Service:** Sweet
Manway: yes **Coating:** No
MAWP **psi** 1724.000 **KPa** **Temp:** (F) 121.000 (C)
Outstanding NCR's No **No #** 0

General

Turnaround 2013

Safety Valves

Side	MAWP (psi)	MAWP (kPa)	PSV No.	Set Press (psi)	Set Press (kPa)	Capacity Imperial	Imperial Units	Capacity Metric	Metric Units
Shell		1724.000	SM083A	250.000	1723.700	6801.000	SCFM	192.580	m3/min
Shell		1724.000	SM084A	250.000	1723.700	6801.000	SCFM	192.580	m3/min

Status In Service **Examination Methods** VT **Access** External **Cleaning** Good

External

Good Condition, no concerns noted on inspection chart.

Internal

No concerns noted on Inspection wall chart.

Recommendations

None

INSPECTOR : I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment detailed here is:

Suitable to be returned to Service Yes **Repairs complete (AB-40 attached)** N/A
Repairs are still required No **Suggested Inspection interval** 60
 Mark Russell, #000101 11/2/2016

Inspector

Signature

Date

CHIEF INSPECTOR: I certify that the information on this report is true and all inspections as required by our Owner/User

Quality Assurance Program # AQP-8094 **which expires in** 02/12/2010 **have been done.**

Owen Baker

11/21/2016

Chief Inspector

Signature

Date