

AM Inspection Ltd.

...Your Non-Destructive Testing Specialists
 Box 463, Cabri, Saskatchewan S0N 0J0
 Toll Free: 1-800-667-6747
 Cabri, SK (306) 587-2620 Fax: (306) 587-2805



Date April 3, 2012
 Page B of 18
 U 013

ULTRASONIC INSPECTION REPORT

CLIENT: Enerplus JOB / WR #: _____
 LOCATION: Miry Bay Compressor Station 16-24-21-19W3 AFE #: _____
 ITEM(S) EXAMINED: _____
 PROCEDURE #: UT Thickness CLIENT PO #: _____
 ACCEPTANCE CRITERIA: _____ SPECIFICATION: _____

EQUIPMENT: Panametrics 26MG S/N: 2761609 CAL DATE: Apr 20, 2011
 CAL. BLOCK (#'S): 200 PN 20TBE 10185562 COUPLANT: ULTRA GEL CABLE LENGTH: _____ IN.
 TEST PIECE: _____ REF. REFLECTOR: _____ Type: _____ Size: _____ Depth: _____ Response Ht: _____
 THICKNESS SHEAR WAVE LAMINATION BABBITT BOND VOLUMETRIC
 SURFACE CONDITION: Clean Bare Metal As Ground Machinec Shot Blast Painted Other _____

	ANGLE	FREQ	SIZE	S/N	RANGE	Ref. dB	Scan dB	Total dB
1								
2								
3								
4								

TEST RESULTS

THICKNESS SEPARATORS (RANDOM)
 - SEE PICTURES FOR THICKNESS VALUES AND LOCATIONS

PLATINUM
 SN# 15148-01
 E-49331

KINETIC
 SN# 505.081.001
 E-49610

COST ESTIMATE

STAMP

JIM CARLETON
 ASNT II
 CGSB.48.9712 L II
 4954

REG HRS	OT HOURS	KM'S	SUB DAYS

Client Signature: _____
 Client Print: _____
 Technician Signature: *[Signature]*
 Assistant Print: *J. PAUL*

AM Inspection Ltd.

...Your Non-Destructive Testing Specialists

Enerplus
Miry Bay Compressor Station
16-24 21-19 W3
April 3, 2012

