



ENGINE REPORT

65102

LOT # _____

MAKE: LUMMAS MODEL: GT4855E S/N: 99800168

INSPECTED BY: Tony Morris DATE: OCT 14 2019

THIS ENGINE POWERS A: Generator

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	☒	☐	<u>couldn't run as</u>
Engine Smoke	☐	☒	<u>E stop is holding out</u>
Turbocharger	☒	☐	<u>panel jumped out</u>
Hour Meter	☒	☐	<u>(5796.8 HRS) switch and ran unit.</u>
After Cooler	☒	☐	<u>put back to how was hand</u>
Fuel Priming Pump	☐	☒	<u>(_____ PSI) will need to be wired properly.</u>
Oil Pump	☒	☐	<u>(62 PSI)</u>
Cooling System	☒	☐	<u>(147 TEMP)</u>

Additional Comments: This has a problem with E stop switch and
would possibly run if trouble was fixed at E stop button
is bad. or way unit was disconnected would cause trouble in
wiring

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.