

## EOG Resources Canada Inc.

## HEVI-WATE SUMMARY REPORT



Date Printed

23-Sep-2014

Start Date: 04-May-2014

Insp. Compl. Date: 04-May-2014

V-1402611-1-1

M.S. Compl. Date:

<b>Division:</b>		<b>HW Type:</b>	Normal	<b>English</b>	<b>Metric</b>	<b>New TJ OD:</b>	6.250	158.8	CollarGuard 5 Record TJ Lengths MPI Center Wear Pad							
<b>Customer Order #</b>		<b>Insp Unit</b>	CU-22	<b>Pipe Size:</b>	4.500	114.30	<b>Min TJ OD:</b>	5.875					149.2			
<b>Rig Name:</b>	Precision 156	<b>Rec. Man.</b>	#1	<b>Weight:</b>	40.8	60.72	<b>Min Box Shld:</b>	---					---			
<b>Oil Comp.:</b>	EOG Resources Canada Inc.	<b>Grade:</b>	N/A	<b>Connection:</b>	4-1/2 XH		<b>Min Seal Wd:</b>									
<b>Well Loc.:</b>		<b>NC#, Range:</b>	NC46 III	<b>Bevel Diam:</b>	5.719	145.3	<b>New TJ Bore:</b>	2.875					73.0			
<b>Insp'd at:</b>	Guardian Plant - Estevan	<b>Nom. Wall:</b>	---	---	---	---	<b>Max Ctr Dia:</b>	---					---			
<b>Inspected By</b>		<b>Misc. #1:</b>		<b>90% Wall:</b>	---	---	<b>Min Ctr Len:</b>	---	---	<b>Drift Size:</b> 0.000 0.000						
1	DeLee Lischka	4		<b>Job Spc:</b>	Precision Spec		<b>80% Wall:</b>	---	---	<b>Hardness Range in HRC Scale</b>						
2		5		<b>Drilled:</b>	---		<b>70% Wall:</b>	---	---	<b>Min Box Len:</b>	---	---	<b>Tube Min:</b>	---	<b>Max:</b>	---
3		6	Jonathan Lewis	<b>Units:</b>	Metric					<b>Min Pin Len:</b>	---	---	<b>T.J. Min:</b>	---	<b>Max:</b>	---
<b>Notes:</b>							<b>New CWP OD:</b>	5.000	127.0	<b>Thread Length</b>						
							<b>Min CWP OD:</b>	4.750	120.7	<b>Box Min:</b>	---	<b>Max:</b>	---			
							<b>Min Tally Len:</b>	---	---	<b>Pin Min:</b>	---	<b>Max:</b>	---			

TUBE						BOX								Centre Wear Pad				PIN										
# Pcs.	Final Class	Colour Code	Req ID Clean	Bent	Short Tally Len.	Short TJ	Poor HB	Re-face	Recut	Bevel	Under Size TJ	Crack	Box Final	Poor HB Box	Poor HB Pin	Box Side Final	Pin Side Final	Short TJ	Poor HB	Re-face	Recut	Bevel	Under Size TJ	Crack	Pin Final			
			Org Band	Wht Band		Blue Upset	Prpl Upset	Grn	Two Green	Purple	Blue	Red	Paint Band	Prpl Upset	Prpl Upset	Paint Band	Paint Band	Blue Upset	Prpl Upset	Grn	Two Green	Purple	Blue	Red	Paint Band			
40	---	---											w			ok	ok								w			
40	TOTALS:		0	0	0	0	0	0	0	0	0	0		0	0			0	0	0	0	0	0	0				
TUBE			R.By Yellow			0	STRAIGHTENED				BENT		SEALS REFACED AND GAUGED O.K.															
Premium	0	R.By Orange			0	Bowed:				0	0	Box/Pin				Box/Pin				Box/Pin								
Yellow	0	Potent. Prem			0	Hooked:				0	0	Galled:				0/0	Stab Mark:				0/0	Handle Mark:				1/0		
Orange	0	Potent. #2			0	Bow/Hooked:				0	0	Chain Mark:				0/0	Over Torque:				0/0	Tapered:				0/0		
Red	0	Potent. #3			0	Abnorm. Bent:				0	0	Washed:				0/0	Pitting:				0/0	Other:				0/0		
R.By Prem.	0	Visual Reject			0	Corkscrewed:				0	0	Stepped:				15/1	Lip:				0/0							
			Not Inspected			40																						
Form 43HW 01-Dec-2000			Tube Total			40	Totals:				0	0	Total Ends Beveled Only:				0/0	Total Seals Refaced:				16/1						