

EOG Resources Canada Inc.

Inspectors:

#1DeLee Lischka

#2

#3

#4

#5

#6Jonathan Lewis

D
A
T
E

Start: 04-May-2014
COMPLETION
Insp: 04-May-2014
M.S.:

Division:

Customer

Order #:

S.O.R. #: V-1402611-1-2

Rig Name, No: Precision156

Oil Company: EOG Resources Canada Inc.

Well Loc.:

Inspected at: Guardian Plant - Estevan

Notes:

InspUnitCU-22

Rec. Man.

#1

#2

#3

#4

H2S Res: ---

Misc. #1:

Job Spc: Precision Spec

Drilled: ---

Units: Metric

Services performed:

CollarGuard 5

Record TJ Lengths

Pipe Size: 4.500

Weight: 40.8

Grade: N/A

Connection: 4-1/2 XH

NC#, Range: NC46

Nom. Wall: ---

90% Wall: ---

80% Wall: ---

70% Wall: ---

Metric

English

114.30

60.72

New TJ OD: 6.250

Min TJ OD: ---

Min Box Shld: ---

Bevel Diam: 5.719

New TJ Bore: 2.875

Max Ctbr Dia: ---

Min Ctbr Len: ---

Max Pn Flt Ln: ---

New CWP OD: ---

Min CWP OD: ---

Min Box Len: ---

Min Box TS: 6.000

Inches

158.8

145.3

73.0

mm

GUARDIAN

A SHAWCOR COMPANY

Hevi-Wate Inspection Report

Printed: 23-Sep-2014Page 1 of 1

Min Pin Len: ---

Min Pin TS: 6.000

Min Tally Len: ---

Drift Size: 0.000

0.000

Hardness Range in HRC Scale

Tube

Min: ---

Max: ---

T.J.

Min: ---

Max: ---

No.	Serial Number	Re-Stamp	Tally Len	Internal Surface	Drifted To	TUBES							CWP				CONNECTIONS																		
						% OD Wear	UT Value	Sono	Wall Gd	Final Class	DEFECT Defect Type; Depth; {Remaining Wall}; Location; ~Tube Comments	Bent	OD	HB Con	Comments	Colour	ID	OD	BB/SRG	TJ Len	TS Len	Bvl Dia	Protector	Thd Cond	Plg Rng Gd	Seal	Refaced	Ctbr / Flat Len	Hardband		Comments	Machine Shop	Colour		
																													Type	Con.					
1	EOG	8	-	4.34	lm	---	--	---	-	-	---		===	---	---		---		161	No	670	---	ok	yes	ok	yes	ok	-	---	---	G		---	w	Box
			--				---	-	-				---	---		---	69.0	161	No	420	---	ok	yes	ok	yes	ok	-	---	---	*Poor		---	w	Pin	

Box/Pin Protectors Missing: 00

Form 23-A 24-Oct-2000

(PRINTED IN ORDER OF INSPECTION)