

EOG Resources Canada Inc.

Inspectors:

#1Terry Walchuk

#2

#3

#4

#5

#6Jonathan Lewis

D
A
T
E

Start: 24-Oct-2014

COMPLETION

Insp: 24-Oct-2014

M.S.:

Division:

Customer

Order #:

S.O.R. #: V-1409936-1-3

Rig Name, No: Precision191

Oil Company: EOG Resources Canada Inc.

Well Loc.:

Inspected at: Guardian Plant - Estevan

Notes:

InspUnitDP-15

#1405866

Rec. #2405864

#3

#4

H2S Res: ---

Misc. #1:

Job Spc: Precision Spec

Drilled: ---

Units: Metric

Services performed:

CollarGuard 5

Record TJ Lengths

Pipe Size: 4.500

Weight: 40.8

Grade: N/A

Connection: 4-1/2 XH

NC#, Range: NC46

Pup

Nom. Wall: ---

90% Wall: ---

80% Wall: ---

70% Wall: ---

Metric

English

114.30

60.72

Inches

mm

New TJ OD: 6.250

158.8

Min TJ OD: 5.875

149.2

Min Box Shld: ---

Bevel Diam: 5.719

145.3

New TJ Bore: 2.875

73.0

Max Ctbr Dia: ---

Min Ctbr Len: ---

Max Pn Flt Ln: ---

New CWP OD: ---

Min CWP OD: ---

Min Box Len: ---

Min Box TS: 6.000

152.4

GUARDIAN

A SHAWCOR COMPANY

Hevi-Wate Inspection Report

Printed: 11-Sep-2015Page 1 of 1

Min Pin Len: ---

Min Pin TS: 6.000

152.4

Min Tally Len: ---

Drift Size: 0.000

0.000

Hardness Range in HRC Scale

Tube

Min: ---

Max: ---

T.J.

Min: ---

Max: ---

No.	Serial Number	Re-Stamp	Tally Len	Internal Surface	Drifted To	TUBES						CWP				CONNECTIONS																			
						% OD Wear	UT Value	Sono	Wall Gd	Final Class	DEFECT Defect Type; Depth; {Remaining Wall}; Location; ~Tube Comments	Bent	OD	HB Con	Comments	Colour	ID	OD	BB/SRG	TJ Len	TS Len	Bvl Dia	Protector	Thd Cond	Plg Rng Gd	Seal	Refaced	Ctbr / Flat Len	Hardband		Comments		Machine Shop	Colour	
																													Type	Con.					
1	EOG	11	-	4.53	lm	---	--	---	-	-	---		===	115	---		---		159	No	620	---	ok	NO	ok	yes	ok	-	---	---	G		---	w	Box
			--				---	-	-			---	---		---	70.0	159	No	450	---	ok	NO	ok	yes	ok	-	---	---	G		---	w	Pin		

Box/Pin Protectors Missing: 11

Form 23-A 24-Oct-2000

(PRINTED IN ORDER OF INSPECTION)