



SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
www.slickinspection.com

MT - PT - UT INSPECTION REPORT - PHOTOS

Technician Sign: _____

Technician Certification:

DARRIN McNEELY
CGSB Level II RT MT
SNT-TC-1A Level II RT MT PT
REG. #6794

Assistant: _____

HAYSYN OSTRUP

Date: _____

JUNE 3 2024

Client: _____

OSL INTEGRATED

Location: _____

TABER, SHOP

| Reg. Hours | O.T. Hours | K.M.s | Sub.. |
|------------|------------|-------|-------|
| - | - | - | - |

Invoice #:

DM24194

Report #:

DM24194U-1

Page:

2 of 2

Acceptance Code:

INFO

Specification:

Procedure:

MT-Rev.5

Technique:

UT - Thickness

Contractor:

OSL INTEGRATED

A.F.E.#:

Code.#:

P.O.#:

Project:

Job.#:

FUELLED INJECTION BUILDING

ITEMS INSPECTED:

INJECTION BUILDINGS PIPING



COMMENTS:

ABOVE ARE PICTURES OF ALL AREAS INSPECTED

Client Rep:

DAVE BROWN

Client Rep Sign: