

Bootis Hill Integrity Management Inc	External Inspection	Form No. 001
Revision # 1	Tank Form (Electronic)	Effective Date: July 1, 2010

Owner	Crescent Point Energy Corp.	Location	16-20-013-20W4	
		Field	Robin	
Tank Data				
Tank Description	Water Tank		Capacity	750 BBL
Manufacturer	Nusco		Elevated	Yes
Manufacturer Date	2001		Heated	Yes
Serial #	004161		Service	Sweet
Tank #			Material	Steel Welded
Insulated	Yes	Type:	Diameter	15'6 Feet
Internal Coating	Yes	Type: Devchem 253	Height	24 Feet
Tank Lined	No	Type:	Wall Type	Double Wall AST
Manway	Yes	Size:	Floor Thickness	1/4 Inches
Secondary Containment	Yes	Type: double wall	Shell Thickness	3/16 Inches
Containment Size (m)	L x W x D = m3		Roof Thickness	3/16 Inches
External Inspection Data				
Facility Signage	YES			
Anodes				
Anode Consumption				
Foundation	2 - Good Used Condition			
Manway Plate	2 - Good Used Condition			
Manway Nozzle				
Nameplate	2 - Good Used Condition			
Bottom Chime	2 - Good Used Condition			
Ground Cable	2 - Good Used Condition			
Lightning Rod Ground	2 - Good Used Condition			
Ladder/Catwalk				
Insulation	2 - Good Used Condition			
Paint Condition	2 - Good Used Condition			
Shell	2 - Good Used Condition			
Roof	2 - Good Used Condition			
Piping	2 - Good Used Condition			
Comments				
Internally inspected 2010-08-21				
Fit for Service	YES			
In Service	YES			
Inspection Interval	5 years Other			
Inspection Type	Visual Internal Other			
Inspector	Milt Tucker			
Inspection Date	21/08/2010			

Milt Tucker

All completed inspection forms go to Brad White – corrosionman@telus.net
All Forms are un-controlled when printed