

Field Inspection Report - Paramount_Resources POU0620_08/26/2010_VT_External

Vessel	POU0620	Vessel	FUEL GAS SCRUBBER	Province	Alberta
Number		Name			
District	GRANDE PRAIRIE BUSINESS UNIT	LSD	03-16-067-22W5	Location	ANTE CREEK
Method	VT	Access	External	Cleaning	Good
Inspection	08/26/2010	Inspection	60	Next	08/26/2015
Date (mm/dd/yyyy)		Interval (months)		Inspection (mm/dd/yyyy)	
CRN	L8912.213T	Skid Number	PKG0607	Service	Sweet
Manway	No	Internal Coating	No	Status	IN SERVICE
MAWP (PSI)	150	MAWP (kPa)	1034.22	Outstanding NCRs	0
MAWT (°C)	37.78	MAWT (°F)	100		

_		_		
ρ	n	ρ	ra	ı

Safety Valves

PSV POU0621 Shell side. Set pressure: 125 PSI / 861.85 KPa. MAWP: 150 PSI / 1034.22 KPa. Capacity: 279 SCFM / 7.47441 m3/hr.

External Condition

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical grounding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and MWS tagging, PSV has correct code stamp, set pressure and MWS tagging, and was last serviced within the required interval guidelines. Assign inspection interval.

Internal Condition

Recommendations

101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Paramount_Resources POU0620_08/26/2010_VT_External

Suitable to be returned to Service	Yes	Repairs complete (AB-40 attached)	N/A
Repairs are still required	No	Suggested Inspection interval (Months)	60
Leo Nedelec Cert 040892			09/02/2010 Date
Inspector		Signature	(mm/dd/yyyy)

Pictures

-No pictures for this inspection-	
I -NO DICIDIES IOLIDIS INSDECTION- I	