

Inspection Report

Client: TURBINE ELECTROMECHANICAL EQUIPMENTS SERVICES LLC	PO No.: N/A
Project Name: TURBINE INSPECTION FOR ENNER FLEX	Location: HMARIYAH
Report No: AQIS/WO 3627/Borescope-29/001-Rev.00	Client Reference: N/A
Date of Inspection: 29-08-2024	Type of Inspection: Remote Visual Inspection (Borescope Inspection)
Aqualis Work Order Number: WO-3627	Vendor RFI Number: N/A

Inspection Details

Details of Inspection:

The following inspection activities have been carried out at TURBINE INSPECTION FOR ENNER FLEX SR NO S10685184 GT-31) **dated on 29.08.2024.**

1. Summary of Inspection:

Remote Visual Inspection (Borescope) has been carried out on TURBINE INSPECTION FOR ENNER FLEX SR NO S10685184 GT-31)

- Inspection Video and photos details as mentioned in this attached link:

Equipment details Used For Inspection:

Make : MITCROP

ID No. : 2AA5FX2000



<input type="checkbox"/>	Material Test Certificate Review	<input type="checkbox"/>	Welder Qualification test witness	<input checked="" type="checkbox"/>	Remote Visual Inspection
<input type="checkbox"/>	Visual & Dimension Inspection	<input type="checkbox"/>	Review Of NDT Reports	<input type="checkbox"/>	RT Film Interpretation
<input type="checkbox"/>	Final Painting Inspection	<input type="checkbox"/>	Final Inspection	<input type="checkbox"/>	Surface Preparation Prior to Painting

Inspector Name: T GOWTHAM

Date: 29-08-2024

Inspection Photos

Inspection Report



Inspection Report

