

# Inspection Report

Client: <b>TURBINE ELECTROMECHANICAL EQUIPMENTS SERVICES LLC</b>	PO No.: <b>N/A</b>
Project Name: TURBINE INSPECTION FOR ENNER FLEX	Location: <b>HMARIYAH</b>
Report No: <b>AQIS/WO 3627/Borescope-29/003-Rev.00</b>	Client Reference: <b>N/A</b>
Date of Inspection: 29-08-2024	Type of Inspection: <b>Remote Visual Inspection (Borescope Inspection)</b>
Aqualis Work Order Number: WO-3627	Vendor RFI Number: <b>N/A</b>

## Inspection Details

### Details of Inspection:

The following inspection activities have been carried out at TURBINE INSPECTION FOR ENNER FLEX SR NO GT S10685184 (TC-31) **dated on 29.08.2024.**

#### 1. Summary of Inspection:

Remote Visual Inspection (Borescope) has been carried out on TURBINE INSPECTION FOR ENNER FLEX SR NO S10685184 (TC-31)

- Inspection Video and photos details as mentioned in this attached link:

#### Equipment details Used For Inspection:

Make : MITCROP

ID No. : 2AA5FX2000

<input type="checkbox"/>	Material Test Certificate Review	<input type="checkbox"/>	Welder Qualification test witness	<input checked="" type="checkbox"/>	Remote Visual Inspection
<input type="checkbox"/>	Visual & Dimension Inspection	<input type="checkbox"/>	Review Of NDT Reports	<input type="checkbox"/>	RT Film Interpretation
<input type="checkbox"/>	Final Painting Inspection	<input type="checkbox"/>	Final Inspection	<input type="checkbox"/>	Surface Preparation Prior to Painting

Inspector Name: T GOWTHAM

Date: 29-08-2024

## Inspection Photos

Quality Assured....

## Inspection Report



Quality Assured....

## Inspection Report

