



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

## Field Inspection Report - Long\_Run 172957\_05/31/2012\_VT\_External

Vessel Number	172957	Vessel Name	NGL BULLET	Province	Alberta
District	TREVOR J'S FIELD	LSD	05-10-033-26W4	Location	WIMBORNE
Method	VT	Access	External	Cleaning	Good
Inspection Date (mm/dd/yyyy)	05/31/2012	Inspection Interval (months)	60	Next Inspection (mm/dd/yyyy)	05/31/2017
CRN	9156.3214	Skid Number	NO	Service	Sweet
Internal Access	YES	Internal Coating	No	Status	IN SERVICE
MAWP (PSI)	250	MAWP (kPa)	1723.7	Outstanding NCRs	0
MAWT (°C)	66	MAWT (°F)	150.8		

### General

### Safety Valves

PSV P95925 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

PSV P95926 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

PSV P95927 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

PSV P95928 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 10203 SCFM / 288.92 m3/min.

### External Condition

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical grounding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. No evidence of short studding or nut rounding.

Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and A# stamping, PSV has correct code stamp, set pressure and MWS tagging, and was last serviced within the required interval guidelines.

Assign inspection interval.

### Internal Condition

---

## Field Inspection Report - Long\_Run

**172957\_05/31/2012\_VT\_External**

---



---

### Recommendations

---

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	60
Repairs are still required	No		
Glen Boettger Cert 000345 Inspector	Signature	06/18/2012 Date (mm/dd/yyyy)	

---

### Pictures

---

