



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run 172957_06/25/1999_VT_EXTERNAL

Vessel Number	172957	Vessel Name	NGL BULLET	Province	ALBERTA
District	CENTRAL ALBERTA	LSD	05-10-033-26W4	Location	WIMBORNE
Method	VT	Access	EXTERNAL	Cleaning	GOOD
Inspection Date (mm/dd/yyyy)	06/25/1999	Inspection Interval (months)	24	Next Inspection (mm/dd/yyyy)	06/25/2001
CRN	9156.3214	Skid Number	NO	Service	Sweet
Internal Access	YES	Internal Coating	No	Status	In Service
MAWP (PSI)	250	MAWP (kPa)	1723.7	Outstanding NCRs	0
MAWT (°C)	66	MAWT (°F)	150.8		

General

Safety Valves

Insert PSV Protection Here

External Condition

VISUAL EXTERNAL INSPECTION REVEALED NO DEFECTS, ASSOCIATED PIPING AND CONNECTIONS VISUALLY INSPECTED WITH NO DEFECTS NOTED. NAMEPLATE IS INTACT, ELECTRICAL GROUNDING AND SUPPORT ALL OK.

Internal Condition

Recommendations

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	24
Repairs are still required	No		



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run

172957_06/25/1999_VT_EXTERNAL

JOHN BOURNE G.I.G. Inspector	Signature	01/23/2007 Date (mm/dd/yyyy)
----------------------------------------	------------------	-------------------------------------------

Pictures

-No pictures for this inspection-
