



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run

557073_04/19/2012_VT_External

Vessel Number	557073	Vessel Name	INLET SEPARATOR	Province	Alberta
District	NORTHERN - AB	LSD	01-25-076-01W6	Location	EAGLESHAM PLANT
Method	VT	Access	External	Cleaning	Good
Inspection Date (mm/dd/yyyy)	04/19/2012	Inspection Interval (months)	60	Next Inspection (mm/dd/yyyy)	04/19/2017
CRN	T6684.2	Skid Number	PKG54820 / V-100	Service	Sweet
Internal Access	YES	Internal Coating	No	Status	In Service
MAWP (PSI)	675	MAWP (kPa)	4653.99	Outstanding NCRs	0
MAWT (°C)	93.33	MAWT (°F)	200		

General

Safety Valves

PSV P80372 Shell side. Set pressure: 550 PSI / 3792.14 KPa. MAWP: 675 PSI / 4653.99 KPa. Capacity: 13910 SCFM / 482.24 m³/min.

External Condition

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical grounding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. No evidence of short studding or nut rounding at time of inspection.

Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and A# stamping, PSV has correct code stamp, set pressure and MWS tagging, and was last serviced within the required interval guidelines.

Assign inspection interval.

Internal Condition

Recommendations



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run

557073_04/19/2012_VT_External

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	60
Repairs are still required	No		
Doug Gohmann, MWS Inspector		Signature	04/24/2012 Date (mm/dd/yyyy)

Pictures

-No pictures for this inspection-
