

Field Inspection Report - Long_Run 3162189_06/01/2011_UT_External

Vessel Number	3162189	Vessel Name	PROPANE SUBCOOLER	Province	Alberta
District	NORTHERN - AB	LSD	03-26-074-01W6	Location	PUSKWASKAU
Method	UT	Access	External	Cleaning	
Inspection Date (mm/dd/yyyy)	06/01/2011	Inspection Interval (months)	60	Next Inspection (mm/dd/yyyy)	06/01/2016
CRN	N1346.2	Skid Number	PKG62777	Service	
Internal Access	No	Internal Coating	No	Status	In Service
MAWP (PSI)	250.05	MAWP (kPa)	1724	Outstanding NCRs	0
MAWT (°C)	66.11	MAWT (°F)	151		

General

Kick off UT report entered only to show next inspection due dates in the database.
UT survey last performed by Probe in 2011.

Safety Valves

PSV P99578 Tube side. Set pressure: 1320 PSI / 9101.14 KPa. MAWP: 1320.01 PSI / 9101 KPa. Capacity: 21007 SCFM / 594.85 m3/min.
PSV P99587 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250.05 PSI / 1724 KPa. Capacity: 15079 SCFM / 426.99 m3/min.

External Condition

Internal Condition

Recommendations

UT due again in 2016.

Field Inspection Report - Long_Run 3162189_06/01/2011_UT_External

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	60
Repairs are still required	No		
Duane Paetkau Cert #000087 Inspector			02/05/2013 Date (mm/dd/yyyy)
		Signature	

Pictures

-No pictures for this inspection-	
-----------------------------------	--