

FORM: IMS001 – Devon Standard Inspection Form

Equipment:			
District:	Fairview	Equipment Name:	Glycol Particulate Filter
Plant / Area:	Puskwaskau	Equipment Number:	95261-AJ
LSD:	3-26-74-1W6	Manufacturer:	Propak
Functional Block (Process Unit):	DPCU	Manufacture Serial Number:	95261-AJ
Equipment Type:	Filter	Provincial Registration Number:	A-445940
CRN:	N1351.2		
Inspection Personnel:			
Inspection Company:	Devon	Extent of Inspection:	Full Internal
Name of Inspector:	Jason McGovern	Date of Inspection:	June 17, 2009
Inspection Summary:			
- Filter had possible corrosion Directly beside where nameplate is located. UT Follow up to be completed.			
Inspection Details:			
<ul style="list-style-type: none"> - Full internal inspection was completed. One area of possible corrosion was noted directly beside nameplate bracket. UT inspection is required. - No external deficiencies were noted. 			
Repairs:			
- None			
NDE Reports:			
<ul style="list-style-type: none"> - Acuren MPI Report M-086670 - No Indications 			
Recommendations:			
<ul style="list-style-type: none"> - UT Inspection as stated above. - 			
Certification:			
Inspector Signature:		Provincial Certification Number:	
Date:	June 18, 2009		

Pictures:	
	
<p>Picture 1 (Desc.):</p>	<p>Picture 2 (Desc.)</p>
	
<p>Picture 3 (Desc.):</p>	<p>Picture 4 (Desc.)</p>
<p>Picture 5 (Desc.):</p>	<p>Picture 6 (Desc.)</p>

Note:

1. Contractor inspector to submit complete inspection form in PDF or word with pictures attached as JPG.
2. Individual pictures must be in a format that is less than 2 MB.