



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

## Field Inspection Report - Long\_Run

### 3174858\_06/18/2009\_VT\_Internal

Vessel Number	3174858	Vessel Name	INLET SEPARATOR	Province	Alberta
District	NORTHERN - AB	LSD	03-26-074-01W6	Location	PUSKWASKAU
Method	VT	Access	Internal	Cleaning	
Inspection Date (mm/dd/yyyy)	06/18/2009	Inspection Interval (months)	48	Next Inspection (mm/dd/yyyy)	06/18/2013
CRN	N1538.2	Skid Number	PKG62774	Service	SOUR
Internal Access	Yes	Internal Coating	No	Status	In Service
MAWP (PSI)	1400	MAWP (kPa)	9652.72	Outstanding NCRs	0
MAWT (°C)	65.56	MAWT (°F)	150		

#### General

Report is entered only to show next internal inspection due dates in the database.

Vessel purchased from Devon.

They assigned 48 month interval at last inspection.

On ABSA ESR as being due for next thorough in 2013.

#### Safety Valves

PSV P102253 Shell side. Set pressure: 1400 PSI / 9652.72 KPa. MAWP: 1400 PSI / 9652.72 KPa. Capacity: 13647 SCFM / 386.44 m3/min.

#### External Condition

#### Internal Condition

#### Recommendations

Vessel due for internal inspection in 2013.



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

---

## Field Inspection Report - Long\_Run

### 3174858\_06/18/2009\_VT\_Internal

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	48
Repairs are still required	No		
Duane Paetkau Cert #000087 Inspector	Signature	02/06/2013 Date (mm/dd/yyyy)	

---

### Pictures

---

-No pictures for this inspection-	
-----------------------------------	--