

Field Inspection Report - Long_Run 565212_04/23/2013_VT_External

Vessel Number	565212	Vessel Name	HORIZONTAL SEPARATOR	Province	Alberta
District	NORTHERN - AB	LSD	06-03-074-04W6	Location	TEEPEE CREEK
Method	VT	Access	External	Cleaning	
Inspection Date (mm/dd/yyyy)	04/23/2013	Inspection Interval (months)	60	Next Inspection (mm/dd/yyyy)	04/23/2018
CRN	T4475.2	Skid Number	PKG56601	Service	Sour
Internal Access	Yes	Internal Coating	No	Status	In Service
MAWP (PSI)	720	MAWP (kPa)	4964.26	Outstanding NCRs	0
MAWT (°C)	37.78	MAWT (°F)	100		

General

Safety Valves

PSV P91334 Shell side. Set pressure: 720 PSI / 4964.26 KPa. MAWP: 720 PSI / 4964.256 KPa. Capacity: 11076 SCFM / 313.64 m3/min.

External Condition

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical grounding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection.

Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and A# stamping, PSV has correct code stamp, set pressure and MWS tagging, and was last serviced within the required interval guidelines.

Assign inspection interval.

Internal Condition

Recommendations



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run

565212_04/23/2013_VT_External

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	60
Repairs are still required	No		
Doug Gohmann, MWS Inspector	Signature		04/23/2013 Date (mm/dd/yyyy)

Pictures

-No pictures for this inspection-	
-----------------------------------	--