

Field Inspection Report - Long_Run 518943_05/30/2012_VT_External

Vessel Number	518943	Vessel Name	SEPARATOR	Province	Alberta
District	TREVOR J'S FIELD	LSD	05-10-033-26W4	Location	WIMBORNE
Method	VT	Access	External	Cleaning	Good
Inspection Date (mm/dd/yyyy)	05/30/2012	Inspection Interval (months)	60	Next Inspection (mm/dd/yyyy)	05/30/2017
CRN	R9068.213	Skid Number	SKD1040	Service	Sweet
Internal Access	NO	Internal Coating	No	Status	IN SERVICE
MAWP (PSI)	1480	MAWP (kPa)	10204.3	Outstanding NCRs	0
MAWT (°C)	37.78	MAWT (°F)	100		

General

Safety Valves

PSV CR0151 Shell side. Set pressure: 1480 PSI / 10204.304 KPa. MAWP: 1480 PSI / 10204.304 KPa. Capacity: 14442 SCFM / 408.95 m3/min.

External Condition

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical grounding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. No evidence of short studding or nut rounding.

Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and A# stamping, PSV has correct code stamp, set pressure and MWS tagging, and was last serviced within the required interval guidelines.

Assign inspection interval.

Internal Condition

Recommendations

Field Inspection Report - Long_Run 518943_05/30/2012_VT_External

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	60
Repairs are still required	No		
Glen Boettger Cert 000345 Inspector	Signature		06/18/2012 Date (mm/dd/yyyy)

Pictures



CRW 518943 NAMEPLATE 05-30-12.JPG



CRW 518943 SEPARATOR 05-30-12.JPG