

Field Inspection Report - Long_Run 518943_06/18/2005_VTI_External

Vessel Number	518943	Vessel Name	SEPARATOR	Province	Alberta
District	CENTRAL ALBERTA	LSD	05-10-033-26W4	Location	WIMBORNE
Method	VTI	Access	External	Cleaning	Good
Inspection Date (mm/dd/yyyy)	06/18/2005	Inspection Interval (months)	48	Next Inspection (mm/dd/yyyy)	06/18/2009
CRN	R9068.213	Skid Number	SKD1040	Service	Sweet
Internal Access	NO	Internal Coating	No	Status	In Service
MAWP (PSI)	1480	MAWP (kPa)	10204.3	Outstanding NCRs	0
MAWT (°C)	37.78	MAWT (°F)	100		

General

Safety Valves

PSV CR0151 Shell side. Set pressure: 1480 PSI / 10204.304 KPa. MAWP: 1480 PSI / 10204.304 KPa. Capacity: 14442 SCFM / 408.95 m3/min.

External Condition

VISUAL EXTERNAL INSPECTION REVEALED NO APPARENT DEFECTS, ASSOCIATED PIPING AND CONNECTIONS VISUALLY INSPECTED WITH NO APPARENT DEFECTS NOTED. NAMEPLATE IS INTACT, ELECTRICAL GROUNDING AND SUPPORT APPEAR OK.

Internal Condition

Recommendations

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	48



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run 518943_06/18/2005_VTI_External

Repairs are still required	No		
Jayson Bourne MWS Inspector	Signature		11/21/2006 Date (mm/dd/yyyy)

Pictures

-No pictures for this inspection-	
-----------------------------------	--