

## Field Inspection Report - Long\_Run 518943\_06/18/2005\_VT\_External

<b>Vessel Number</b>	518943	<b>Vessel Name</b>	SEPARATOR	<b>Province</b>	Alberta
<b>District</b>	CENTRAL ALBERTA	<b>LSD</b>	05-10-033-26W4	<b>Location</b>	WIMBORNE
<b>Method</b>	VT	<b>Access</b>	External	<b>Cleaning</b>	Good
<b>Inspection Date (mm/dd/yyyy)</b>	06/18/2005	<b>Inspection Interval (months)</b>	60	<b>Next Inspection (mm/dd/yyyy)</b>	06/18/2010
<b>CRN</b>	R9068.213	<b>Skid Number</b>	SKD1040	<b>Service</b>	Sweet
<b>Internal Access</b>	NO	<b>Internal Coating</b>	No	<b>Status</b>	In Service
<b>MAWP (PSI)</b>	1480	<b>MAWP (kPa)</b>	10204.3	<b>Outstanding NCRs</b>	0
<b>MAWT (°C)</b>	37.78	<b>MAWT (°F)</b>	100		

### General

### Safety Valves

PSV CR0151 Shell side. Set pressure: 1480 PSI / 10204.304 KPa. MAWP: 1480 PSI / 10204.304 KPa. Capacity: 14442 SCFM / 408.95 m3/min.

### External Condition

VISUAL EXTERNAL INSPECTION REVEALED NO APPARENT DEFECTS, ASSOCIATED PIPING AND CONNECTIONS VISUALLY INSPECTED WITH NO APPARENT DEFECTS NOTED. NAMEPLATE IS INTACT, ELECTRICAL GROUNDING AND SUPPORT APPEAR OK.

### Internal Condition

### Recommendations

<b>Suitable to be returned to Service</b>	Yes	<b>Suggested Inspection interval (Months)</b>	60



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

## Field Inspection Report - Long\_Run 518943\_06/18/2005\_VT\_External

<b>Repairs are still required</b>	No	
Jayson Bourne MWS <b>Inspector</b>	<b>Signature</b>	06/18/2005 <b>Date (mm/dd/yyyy)</b>

### Pictures

-No pictures for this inspection-