

Field Inspection Report - Long_Run 518943_12/12/2004_VTI_External

Vessel Number	518943	Vessel Name	SEPARATOR	Province	Alberta
District	LEASE	LSD	00-00-000-00W0	Location	CALGARY
Method	VTI	Access	External	Cleaning	Good
Inspection Date (mm/dd/yyyy)	12/12/2004	Inspection Interval (months)	36	Next Inspection (mm/dd/yyyy)	12/12/2007
CRN	R9068.213	Skid Number	8000307	Service	
Internal Access	No	Internal Coating	No	Status	Stock
MAWP (PSI)	1480	MAWP (kPa)	10204.3	Outstanding NCRs	0
MAWT (°C)	37.78	MAWT (°F)	100		

General

The vessel static data and PSV data was gathered and VT external done. A unique identifier was attached where necessary.

Safety Valves

Insert PSV Protection Here

External Condition

The vessel was plumb and level as was the piping. The support was good and was grounded. The shell, where seen, was in good condition.

Internal Condition

Recommendations

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	36
Repairs are still required	No		



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run 518943_12/12/2004_VTI_External

Don Jacklin Cert 000049 Inspector	Signature	12/23/2004 Date (mm/dd/yyyy)
---	------------------	--

Pictures

-No pictures for this inspection-	
-----------------------------------	--