



# Clear Image Inspection Ltd.

PO Box 786, Bentley, AB, TOC OJO

Office: (403) 748-4703  
admin@clearimageinspection.com

## Radiographic Inspection Report

**RT Report #** 251215-RS-1-RT1 **Daily Cost Report #** 251215-RS-1-DCR1

**Client:** E&M Oilfield Services Ltd. **Date(YYYY-MM-DD):** 2025-12-15 **Source of Radiation:** Ir192 **Number Film per Cassette:** 1

**Location:** Sylvan shop **Examination Standard:** CSA 7.13, 7.14 **Source Size:** 0.125" **Radiography Examination:** CSA Z-662

**Client PO/AFE#** PUMP #1 **Acceptance Standard:** CSA Z-662-23 **Film Class:** ASTM 1 **Procedures Manual:** Section 9

**Client Job#** 14-25 **Material Type:** P1 **Film Manufacturer:** Carestream **Revision #:** 1

**Abbreviations:** IP-Incomplete Penetration LOF- Lack of Fusion CK-Crack P-Porosity S-Slag HB-Hollow Bead EP-Excess Penetration  
IC-Internal Concavity IUC-Internal Undercut EUC-External Undercut LC-Low Cover BT-Burn Through 1-Slight 2-Moderate 3-Reject


Weld Info			Radiograph Info			Defects											Results				
Weld ID	Weld Size	Welder ID	Procedure	Number of Exposures	Film	IP	LOF	CK	P	S	HB	EP	IC	IUC	EUC	LC	BT	Defect Location/ Comments	✓	✗	
1																					
2	XF-6R1	JP	RT-1	3	MX125														✓		
3																					
4																					
5																					
6																					
7																					
8																					
9																					
10																					
11																					
12																					
13																					
14																					
15																					
16																					
17																					
18																					
19																					
20																					
21																					
22																					
23																					
24																					
25																					

Interpretation is in accordance with the above referenced standards, to the best of my professional ability.

**Technician Name:** Ryley Sieben **RT CGSB Level:** II **NRCAN Reg.#** 17447 **Client Representative:** Ernie Jacobson

**RT SNT Level:** II

**Assistant Name:** \_\_\_\_\_ **NRCAN Reg.#** \_\_\_\_\_

**Technician Signature:**  **Client Signature:** \_\_\_\_\_

The above representation is a professional opinion, final interpretation and acceptance of film and reports are the responsibility of the client. I have reviewed and am in full agreement with the contents of this report.