

Field Inspection Report - Long_Run 568797_03/09/2014_VT_External

Vessel Number	568797	Vessel Name	BULLET	Province	Alberta
District	NORTHERN - AB	LSD	07-04-071-18W5	Location	SNIPE LAKE
Method	VT	Access	External	Cleaning	Good
Inspection Date (mm/dd/yyyy)	03/09/2014	Inspection Interval (months)	60	Next Inspection (mm/dd/yyyy)	03/09/2019
CRN	A223.4.5.3.2.8.0	Skid Number	N/A	Service	SWEET
Internal Access	Yes	Internal Coating	No	Status	In Service
MAWP (PSI)	250	MAWP (kPa)	1723.7	Outstanding NCRs	0
MAWT (°C)	53.33	MAWT (°F)	128		

General

Safety Valves

PSV P110884 Shell side. Set pressure: 250 PSI / 1723.7 KPa. MAWP: 250 PSI / 1723.7 KPa. Capacity: 6515 SCFM / 184.48 m3/min.

External Condition

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical grounding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. No evidence of short studding or nut rounding at time of inspection. Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and A# stamping, PSV has correct code stamp, set pressure and MWS tagging, and was last serviced within the required interval guidelines. Assign inspection interval.

Internal Condition

Recommendations



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run

568797_03/09/2014_VT_External

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	60
Repairs are still required	No		
Leo Nedelec Cert 040892 Inspector	Signature		03/25/2014 Date (mm/dd/yyyy)

Pictures

-No pictures for this inspection-	
-----------------------------------	--