

Field Inspection Report - Long_Run 640530_02/09/2017_VT_Internal

Vessel Number	640530	Vessel Name	TREATER	Province	Alberta
District	CENTRAL - AB	LSD	02-12-058-23W4	Location	REDWATER NORTH
Method	VT	Access	Internal	Cleaning	
Inspection Date (mm/dd/yyyy)	02/09/2017	Inspection Interval (months)	48	Next Inspection (mm/dd/yyyy)	02/09/2021
CRN		Skid Number		Service	Sweet
Internal Access	Yes	Internal Coating	No	Status	In Service
MAWP (PSI)		MAWP (kPa)		Outstanding NCRs	0
MAWT (°C)		MAWT (°F)			

General

Treater installed in 2017.
This report entered only to show initial internal inspection due dates in the database.
Due for initial internal inspection in 2021 as per ABSA AB-506.

Safety Valves

Insert PSV Protection Here

External Condition

Internal Condition

Recommendations

Due for initial internal inspection in 2021 as per ABSA AB-506.

Suitable to be returned to Service	Yes	Suggested Inspection interval (Months)	48
Repairs are still required	No		



101, 56 Cuendet Industrial Way, Sylvan Lake, AB T4S 0B6

Field Inspection Report - Long_Run 640530_02/09/2017_VT_Internal

Duane Paetkau ABSA ISBPV:000087, API 570:24422, NB Cert. 222 Inspector	Signature	02/09/2017 Date (mm/dd/yyyy)
--	------------------	--

Pictures

-No pictures for this inspection-