

# Storage Tank Internal Visual Inspection Report



Organization: Husky

Inspection Date: 14/01/2009 12:00:00AM

Plant: Northwest Alberta

Equipment ID: 66137027

Asset No: 66137027

System: N/A

Operating Unit: LAIDUP AND SURPLUS

## Background

Description:	TANK, AST, 400 BBL, DW, WATER STORAGE
--------------	---------------------------------------

## Inspection

Inspector:	ROMAN WYNNYK	Company:	N/A	Internal Lining/Coating:	
------------	--------------	----------	-----	--------------------------	--

## Inspection Comments

ID	Description	Condition	Location	NCR	Comments
ROMAN WYNN		N/A			-NO VISUAL INTERNAL INSPECTION PERFORMED AS TANK WAS INSTALLED IN WINTER OF 2007/08 AND IS ONLY USED FOR THE WINTER MONTHS. (WINTER ACCESS ONLY)

## Inspection Summary

-NO VISUAL INTERNAL INSPECTION PERFORMED AS TANK WAS INSTALLED IN WINTER OF 2007/08 AND IS ONLY USED FOR THE WINTER MONTHS. (WINTER ACCESS ONLY)

## **Storage Tank Internal Visual Inspection Report**

### **Inspection Planning**

Date of Inspection: \_\_\_\_\_ Date of last Inspection: \_\_\_\_\_ Date of Next Inspection: \_\_\_\_\_

The signature below certify that the above is a true report of the inspection / test of the equipment specified and consider fit for service until the date of next inspection.

Competent Inspector: \_\_\_\_\_ Report Generation Date: \_\_\_\_\_

### **Reviewed and Accepted by:**

Next Inspection Date: \_\_\_\_\_

### **Approved by:**

Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Signature: \_\_\_\_\_ Date: \_\_\_\_\_