

Head Office: PO Box 1480
7201-50 Ave, Stettler, AB T0C 2L0
Toll Free 1.877.742.6900

Job 143819

Customer Instructions:

Desc. of Problem & Solution:

Receive Permit

Dr. Zunning

test, ALL Beta

filter kept a/c

Tested Cais #

Bearings

10

100

100

Helper: _____

Nelson

Technician: x 

Travel & Labour

--	--

[illegible]

Date	Begin	Finish
	07/08	08/02

01000000

--	--	--	--

--	--	--	--

--	--	--	--	--

total	Yellow	Control Job	Control Job
100	100	100	100

Customer Unit #: Booster Other #: _____

Unit	Engine	Compressor
Make:		
Model:		
Serial #:		
Hours:		

Customer Instructions: Service Booster
 Desc. of Problem & Solution: Morning Meeting, Grab Parts, Drive to Location, P114
Receive Permit, Drive to 3-7 from Plant
Do Running Checks, Get oil Sample, Shut unit down Do Camp
Test, All Between 190-200 PSI, Do valve set, Drain Oil, Replace
Filter, Replaced valve cover gasket and Crank Case Breather
Tested Cols #1 was weak, Replaced #1 Coil, Greased All Fan
Bearings

	Shop	Field	Complete	WIP
Helper:				
Techician:	x			
Crew Leader:				
Trainer:				
Trainee:				
Customer:				x

Travel & Labour

[illegible]