

Item Name: AIR-X-CHANGER
Location: MANNVILLE
Equip #: A16-01-00E-A2988261
Service: SWEET GAS

Test Date: 5/21/98
Prov #: A2988261
CRN #: K2766.2
Tag #:

Type of Inspection: VI Yes UG PT HT
VIN VE Yes LT RT
MT Other:

Scope: EXTERNAL
Cleaning: NONE
Access: NONE

Observations

Summary:

The equipment was in operation at the time of the external inspection.

Details:

There were no concerns regarding the aerial cooler. The pressure relief valve (552) used to protect the cooler was last serviced (97/5/27).


Recommendations

Summary:

The equipment was found suitable for further operation.

Details:

The pressure relief valve will be due for servicing in (1999).

xx  Chris Harris

Suitable For Service: Yes
Follow Up Required: No
Inspector: MK/LB

Remedial Action Priority:

Date: 5/21/98