



**Husky Oil**

*Pett  
Lana*

1

*4-18-91-25w3.*

May 9, 2002

Municipal Affairs and Housing  
Boiler and Pressure Vessel Safety  
9<sup>th</sup> Floor, 1223<sup>rd</sup> Ave  
North Saskatoon, Saskatchewan  
S7K 2H6

Attention: James Amanie

Please find attached a number of RJV gas field services Ltd. manufactured (2) phase gas separators which have recently been put in service in our Saskatchewan areas. These 2 phase separators have CRN numbers H6948.23 and have a size of 508mm X 1524mm. Should any further questions arise please call me at 825-1221.

Edwin Rogoz  
Sr. QA Technologist



62048705

## BOILER AND PRESSURE VESSEL STATUS REPORT

This status report form has been provided for you to report any changes to your boilers and/or pressure vessels. If you complete the form below, we would be pleased to make the required changes to our records and credit your account if credits are due.

RE: Vessel (A)

1) 475057

2) Size 508mm 3)

Serial No.

6831

X 1524 mm

CRN

H6948.23

☒ The above vessel(s) was (were) sold. Please transfer the registration of the vessel(s) to:

Name of New Owner: Husky Oil Operations Ltd.

Mailing Address: 4429 - 44 STREET, LLOYDMINSTER, SK.

Location of Vessel: 4-18-51-25-W3M

Contact Person: Reg Bevan

Tel: Unit # 7586

Date of Sale: August 3, 2001

P.O. No: 4500061797

- ☐ The above vessel(s) was (were) removed from service on \_\_\_\_\_  
I will advise Alberta Boilers Safety Association when it is returned to service.
- ☐ The above vessel(s) was (were) destroyed and disposed of as scrap material on \_\_\_\_\_  
(Date). The Alberta Identification (A) Number has been obliterated.
- ☐ The above vessel(s) has (have) been relocated to \_\_\_\_\_
- ☒ The above vessel(s) has (have) been operating outside of the Province of Alberta since  
October 15, 2001 (Date). Please remove from annual registration.

Company Name: RJV Gas Field Services Ltd.

Position Title: Office Clerk

Tel: 780-632-7774

(Please print name) Sharlene Zukiwsky

Signature: Szukiwsky

Date: August 9, 2001

Note: The owner of the boiler or pressure vessel is responsible for ensuring that the above equipment is inspected by Alberta Boilers Safety Association prior to its being returned to service in the Province of Alberta.

Please Return This Report To: ALBERTA BOILERS SAFETY ASSOCIATION  
#200, 4208 - 97 Street, Edmonton, AB T6E 5Z9  
(780) 437-9100 Fax (780) 437-7787



HUSKY OIL

FORM: IR-EP-1.7  
REV: 0, DATE: 11/94

# EQUIPMENT RELOCATION NOTIFICATION

FACILITY ..... DATE 02/28/09... REPORT #.....

PRESENT HUSKY LOCATION: New

NEW HUSKY LOCATION: Tangleflag 4-18-51-25 W3M

Equipment ID #	Equipment Description	Prov. Insp. #	CRN	Serial #	Manufacturer	Year Built	MAWP (kPag) @ C	Present WP (kPag) @ C	Present Service	New WP (kPag) @ C	New Service	PSV Setting (kPag)
	PSV 2	475057	H 6948.	6831	RTSV	2001	4820 @		See			4820
	phase		23				300					
	regulator											

REPAIRS/ALTERATIONS YES ☐ NO ☐

INSTALLATION INSPECTION  
COMPLETED YES ☐ NO ☐

Procedure:

Comments: New equipment

Repair / Alteration Report # (s):

Vessel size 508 mm X 1524 mm

VERIFIED BY

Distribution:

E. Ragsdale  
Quality Inspector

Facility Lead Inspect

Facility Technical Leader

*James -  
Used new  
equipment & de  
if already not  
in place they'd*



Tanglelog 4-18-51-25W3M

Vert. 2 phase Separator

BSV Set @ 720 psi

UV Stamp

Model 5800

S/N 46523

Size 1" x 1"

Date 02/02/98 ← Service corp

Cap 1944 SCFM 2001/10/15

RTV Scrubber

CAN OH 0102.23

6725KPA

BSV UV Stamp

Set Press 150 psi

Cap

Date 08/01

S/N 833-42-6 ← Service corp

2001/10/15