

62048705

Report Number: 222005
Previous Inspector:
Licence Number: 25307 - (Acceptance Pending)
Serial - Unit Number: 6831 - A11448
Plant: 0 (pieces)

Equipment:

Bld/Oilfield: Tangleflags
Address: 04-18-51-25W3M
City/Town:
LLD: 04-18-51-25W3M
Community:
District: 5

Owned By:

Husky Energy - Lloyd (2) (306) 820-4032 (Phone)
4335-44th Street
Lloydminster (Sask), Saskatchewan
S9V 0Z8
Canada
C/O Ray Trachuk
OFF 306 625 1234
CELL 260 205 2092

Item Type: 04 - Gas / Oil Separator (Provincial)
Inspector Description:
Owner Description:
CRN: H6948 23 Mobility: Stationary
NB: Shell WP: 4965
Manufacturer: R/V Gasfield Services Tube WP:
Manufactured Date: 2001-01-01 Diameter (m): 0.51
Last Internal Insp.: Length (m): 1.52
Inspection Method: Acceptance
Next Inspection Date: 2018-01-29 (yyyy-mm-dd) Install Permit No.: 19375
Assigned to Inspector: 0445 - Larry Holuk
Previous Conditions:

Inspection Conditions: A - Acceptable R - Repairs or Corrective Action Required N - Not Applicable
C - Comments or Recommendations I - Incomplete/Object Not Exposed/Not Operating

- | | | |
|------------------------------------|--|-------------------------|
| 1. Safety Valve: <u>A</u> | 7. Inspection Openings: <u>A</u> | 13. Nameplate: <u>h</u> |
| 2. Level Gauge: <u>N</u> | 8. Associated Piping: <u>A</u> | 14. Other: <u> </u> |
| 3. Pressure / Temp Gauge: <u>A</u> | 9. Shell: <u>A</u> | |
| 4. Tubesheet: <u>N</u> | 10. Heads: <u>N</u> | |
| 5. Tubes: <u>N</u> | 11. Data Report: <u>N</u> | |
| 6. Insulation: <u>N</u> | 12. Sask Design Registration: <u>A</u> | |

Comments/Repairs or Corrective Action Required:

Unable to do inspection on: (yyyy-mm-dd)

Reason inspection was not done:

Items Classified with an "R" must be repaired or corrected by : (yyyy-mm-dd)
and the Boiler and Pressure Vessel Safety Unit must be notified in writing by fax or mail.
Please include the Licence No. and the Serial Number on all correspondence.

(306) 787-1443 Phone/1-866-530-8599 (Phone - Toll free in SK)
(306) 787-9273 Fax/1-866-760-9255 (Fax - Toll free in SK)

- ☐ This report was discussed with the owner or his representative.
☒ A copy of this report was mailed to the owner/representative by regular mail on: (yyyy-mm-dd)

2013-01-29

Signature of Person receiving report

Inspection Date (yyyy-mm-dd)

Holuk, Larry
952, 122 3rd Avenue North
SASKATOON Saskatchewan S7K 2H6
(306) 933 - 5073 (Work)
(306) 220 - 3195 (Cell)
Larry.Holuk@tsask.ca (Email)

Signature of Inspector

Inspector Number

CLIENT