Husky Energy

WCP MAINTENANCE

DATE mant 24/19

ENGINE SERVICE REPORT

EDSON

COMPANY NAME	WORK ORDER NUMBER	LSD NUMBER	UNIT TAG NUMBER	
HUSEX Bragy	60587347	3-6-49-18WS	C-250	

NAME:

MAKE	MODEL	SERIAL NUMBER	HOURS	
Colorlesna	5774LT	C-1833411	59286	

ENGINE HOURS OF SERVICE:

VALVE SET DATA	INTAKE VA	ALVE OEM SPEC:		EXHAUST VALVE	OEM	SPEC:	
CYLINDER	VALVE	AS LEFT.000	BOROSC	OPE COMPLETED	1	COMMENTS	
1	INTAKE	HAG		ncerns found		SOLVIIVIEI (1)	I
	EXHAUST	HAD		1			÷
2	INTAKE						
2	EXHAUST			*			
3	INTAKE						174
	EXHAUST						
4	INTAKE					7	119
	EXHAUST						
5	INTAKE			1			
T II	EXHAUST						
6	INTAKE				-		
= 8	EXHAUST			2			
7	INTAKE					a y	
	EXHAUST					8 ,	-
8	INTAKE						\dashv
	EXHAUST			KI		*	-
9	INTAKE						\dashv
	EXHAUST					-	-
10	INTAKE						-
	EXHAUST						\dashv
11	INTAKE						-
	EXHAUST	V		0		STANDARD TO THE STANDARD STAND	-

12	INTAKE	
	EXHAUST	
13	INTAKE	
	EXHAUST	
14	INTAKE	
	EXHAUST	
15	INTAKE	
	EXHAUST	
16	INTAKE	
	EXHAUST	

ADDITIONAL ENGINE SERVICE NOTES

No Bolescop concerns CMH Internals look good

ENGINE OPERATING CONDITIONS AS LEFT

ENGINE OIL PRESSURE	352 KeA
ENGINE OIL TEMP	75°C
FUEL PRESSURE	6.4KB 6.8LB
CRANKCASE PRESSURE	-01812HD
ENGINE JACKET WATER	
ТЕМР	78°C
ENGINE NDE VIBES	SIMMPS comp
ENGINE ND VIBES	SIGMMES comp 10.3 MMPS Englise
ENGINE EXHAUST	ENGINE EXHAUST
TEMPERATURES	TEMPERATURES
1]	9]
2]	10]
3]	11]
4]	12]
5]	13]
6]	14]
7] .	15]
8]	16]
t _e	
L1 \$83	R1° 5 76
L2 590	R2 570
L3 591	R3 572
14 592	R4 571
L5 60S	
L6 579	R5 574 R6 576
L7	R7
L8	R8
The state of the s	

ENGINE SERVICE DETAILS

COMPONENT	REPLACE/REPAIR		INSPECTED	COMMENTS	
	YES NO				
ENGINE OIL					
ENGINE FILTER	/				
FUEL FILTERS			OutA	ordered correct for next service	
SPARK PLUGS	V				
EXTENTIONS			Replaced 2		
AIR FILTERS					
COILS			V		
PRIMARY LEADS					
SECONDARY LEADS					
HYDRAULIC LIFTERS					
VALVE COVER GASKETS	✓				
AD VALVES	diam',		heaving ADD average with P		
CARB DIAPHRAMS L/B			V,		
CARB DIAPHRAMS R/B					
CARB BUTTERFLIES					
GOVERNOR					
GOVERNOR LINKAGE	/		V		
MAIN WATER PUMP					
AUX WATER PUMP					
ENGINE JACK SHAFT BELTS			V	Tensioned outside beits	
DRIVE BELTS					
TURBOCHARGERS					
GOVERNOR OIL			V	e ^t .	
COOLER FAN PITCHED			man and the second seco	1 2	
GREASE J/S BEARINGS			/	*	
ADDITIONAL ITEMS 0				8314	
				1.14.1	

ADDITIONAL NOTES

Ensure crank small fator was loose-recomed replace