PETROCUMANA Oil and Gas

WESTERN CANADA UPSTREAM INSPECTION PROCEDURES FOR OIP

Oir aira Quo	THE LONGIT ROOLDONED FOR OH
PROCEDURE No.	SUBJECT
IP-300	PROCESS VESSELS

50-0113-V-801 750 VS 113B Produced Wester Flish Vessel

CHECKLIST #1 - EXTERNAL INSPECTION

1.	Ladders, stairways, platforms and walkways	□ WIA
2.	Foundations and supports	
3.	Nozzles	
4.	Grounding connections	WSKV
5.	Protective coatings and insulation	
6.	External metal surfaces	9
7.	Pressure relief devices	
3.	Name plate	
€.	Ultrasonic thickness survey	To be add to Surry
0.	Inspection report completed	- ma
1.	Nonconformance report completed	□ NIA

APPROVAL
CHIEF INSPECTOR MAY, 1999

REVISION


50-0113-DEC 2003

V-801



50-0113-DEC 2003

V-801



50-0113-DEC 2003

V-801

