



PSV Final Inspection Test Report

5811 - 2nd Ave Edson, AB, T7E 1L8
Phone: (780) 712-4055 Fax: (780) 723-5979

INITIAL INSPECTION	REFERENCE DATA	Date: <u>20-Sep-17</u> W.O.: <u>23781</u> ID: <u>7</u> Customer: <u>Husky Oil</u> Location: <u>05-05-50-19 W5M</u> Field <u>ANSELL (D/H:02-08)</u> Make: <u>TAYLOR</u> Model: <u>82E8351311</u> S/N: <u>012392-260</u> Other S/N _____ Inlet: <u>Threaded</u> Size <u>1.00</u> in. Outlet: <u>Threaded</u> Size <u>1.00</u> in. Orifice: <u>E</u> Tag: <u>SAP#66182404</u> Set Pressure <u>1440</u> PSI <u>9929</u> KPA Back Pressure: _____ PSI _____ KPA Cold/Diff Set Press: _____ PSI _____ KPA Cap Assembly: <u>Closed</u> Lift Lever: <u>No</u> Capacity: <u>5,180</u> SCFM Temp: _____ Tag G: _____ Code Symbol: <u>UV</u> CRN: <u>0G01316.2C</u> Vessel ID: <u>SEPARATOR</u> Vessel No: <u>A611145</u>									
	Customer Instructions: <u>Pretest & Repair</u> Reset Required ☐										
	New Pressure: PSI KPA New Capacity:										
	Pretest: Simmer : <u>1400</u> PSI <u>9,653</u> KPA Set Pressure : <u>1404</u> PSI <u>9681</u> KPA Reseat : <u>1241</u> PSI <u>8556.695</u> KPA Test Gauge ID: <u>Dig 1</u> <u>1-3000</u> Tested By: <u>AW</u> Leakage: <u>0</u> BPM Comments:										
CONDITION RECEIVED	Visual Condition <u>Minor</u> Other: _____ Data Plate: <u>OK</u> Seal Condition: Top: <u>Intact</u> Bottom: <u>NA</u> Insignia: <u>WIZ</u> Date of Last Service: <u>2/9/2012</u>										
	Indicate Fouling <u>Rust</u> INLET ☒ OUTLET ☒ BODY ☒ BONNET ☐ Blow Down Ring Setting (Upper) _____ No. of Notches: (Lower) _____										
CRITICAL INSPECTION	COMPONENTS INSPECTION										
	ITEM		CONDITION		COMMENTS		REPAIRS		OK	REPLACE	
	Disc	Min= Act=	Rusty	CLEANED & INSPECTED			☒	☐			
	Nozzle	Min= Act=	Rusty	CLEANED & INSPECTED			☒	☐			
	Cap/Lever Assembly		Rusty				☒	☐			
	Comp. Screw/ Lock Nut		Rusty				☒	☐			
	Spring and Buttons		Rusty				☒	☐			
	Spindle/Stem		Rusty				☒	☐			
	Disc Holder		Rusty				☐	☐			
	Guide/Upper Ring		Rusty				☒	☐			
	Lower Ring		Rusty				☐	☐			
	Ring Pin(s)		Rusty				☐	☐			
	Bellows		Rusty				☐	☐			
	Gaskets/Seals		Rusty	WORN	REPLACED		☐	☒			
	Connection Ends		Rusty				☒	☐			
	Studs and Nuts		Rusty				☐	☐			
	Other		Rusty				☒	☐			
DISMANTLE: <u>AW</u> INSPECTION: <u>AW</u> REASSEMBLY: <u>AW</u>											
FINAL TEST	MEDIUM : <u>Air</u> SET PRESSURE DEIFINITION <u>Pop</u> FINAL TEST Simmer <u>1440</u> PSI <u>9929</u> KPA Set Press <u>1445</u> PSI <u>9963</u> KPA Reseat <u>1263</u> PSI <u>8708</u> KPA Leakage <u>0</u> BPM BACK PRESSURE TEST <u>60</u> PSI <u>414</u> KPA ADJ. RING SETTING (NOTCHES) UPPER _____ LOWER _____ Test Gauge ID: <u>Dig 1</u> <u>1-3000</u> Tested By: <u>RB</u> Date Tested: <u>21-Sep-17</u>										
FINAL INSPECTION	SEAL INSTALLED: TOP ☒ BOTTOM ☐ FLANGE/ THREAD PROTECTORS INSTALLED ☒ PRIMED / PAINTED ☒ COMMENTS :										
	FINAL INSPECTION: <u>AW</u> CUSTOMER/INSPECTION										