

Please submit to: 9410 – 20<sup>th</sup> Avenue Edmonton, AB T6N 0A4 Tel (780) 437-9100 Fax (780) 437-7787

AB-10 2009-06

## **BOILER AND PRESSURE VESSEL STATUS REPORT**

NOTE:	This form may be used to provide notification of changes in ownership, location, operating status or scrapped boilers and pressure vessels.			
	Please review the respons		the new owner und vebsite www.absa.	der Section 36 of the Pressure Equipment ca)
Re: Ve	essel (A) 1) 6174	195 2)		3)
Serial	-			
CRN	<del></del>	17.231		
	Vessel(s) <b>sold or purchased</b> . Please transfer the registration of the vessel(s) to:  Name of New Owner: Husky Oil Operations Limited			
	Mailing Address:	P.O. Box 4490 Station D	; Calgary, Alberta;	T2P 3G7
	New Location of Vessel:	L.S.D.#.03-14-050-19W5	5	
			(Street Addre	
	Contact Person:		Tel:	403-298-6111
	E-Mail:	Unit # 15500		0.400500570
	Date of Sale:	January 18, 2013	PO No.:	8400580579
	Vessel(s) <b>removed from service</b> on:  (The owner is responsible for ensuring the vessel is inspected by ABSA prior to it being returned to service in the Province of Alberta.)  The above vessel(s) <b>returned to service</b> on:			
	• •	<del></del>	·	
	Inspected on:	(	,	ion Report attached
	Vessel(s) relocated to:		(Street Addres	ss or LSD)
	We <u>own</u> but do not know the location of this vessel. (ABSA records will record the location as unknown, and the applicable annual fee(s) will remain in force to your account. Responsibility for safe operation in Alberta continues to reside with your company. When the location become known, you are required to notify ABSA.)			
	We <b>sold this vessel(s) but do not know to whom</b> . (ABSA records will retain your company name as the owner. Responsibility for safe operation in Alberta also remains with your company until new ownership details are received by ABSA.).			
	. ,	ide of the Province of Al		(Date). Please
remove from annual registration. You are required to notify ABSA if the vessel returns to service in Alb				e vessel returns to service in Alberta.
Vessel Scrapped – All three conditions below must be satisfied				
☐ Vessel has been removed from service and there is no intention to return it to pressure service.				
The nameplate has been removed and all other identification has been removed.				
The vessel is in a condition that it cannot be pressurized. i.e. A hole has been cut in the vessel, or a nozzle has been removed, or a head has been cut off.				
(	Company Name: RJV Ga	as Field Services		
	Position Title: Recept	ionist/Admin.Asst	Tel: <u>780-63</u>	2-7774
(Ple	ase print name): Alice S	tasiuk	E-mail: _alice.st	asiuk@rjvgas.com
	Signature:		Date:	24, 2014