

Equipment #: 66150924
Area: AN-Blackfoot
Cost Centre:

Page 2 of 2



Tank Inspection Report

Approver: Dee Nelson
Requisitioned By: Roger Skoldrood
Manufacturer: Universal
Capacity: 1000 bbl

Approver #: 22-2000425
Location: 104/8-30-48-1 W24
Serial #: 16041-17
Thickness: Floor 1/4 Shell 1/4 3/16
WO#: 4091090
PO#: 8400749718
Tank Type: Heavy Oil Storage
Year Built: 2008

External Inspection

T61	Insulation	<u>GOOD</u>	FAIR	POOR
T64	Cladding	<u>GOOD</u>	FAIR	POOR
T32	Base / Landscaping	<u>GOOD</u>	FAIR	POOR
T14	Liner / Containment	<u>GOOD</u>	FAIR	POOR
T8	Ground Cable	<u>YES</u>	NO	
T6	Ladder/ Stairway	<u>GOOD</u>	FAIR	POOR
T7	Platform	<u>GOOD</u>	FAIR	POOR
T41	Piping Alignment	<u>GOOD</u>	FAIR	POOR
T15	Shell	<u>GOOD</u>	FAIR	POOR
T44	Envirovault	<u>YES</u>	NO	
T16	Roof	<u>GOOD</u>	FAIR	POOR
T11	Paint	<u>GOOD</u>	FAIR	POOR

N/A

In Containment

ENTERED
301-29

Good

N/A

Internal Inspection

T11	Floor	<u>GOOD</u>	FAIR	POOR
V9	Shell	<u>GOOD</u>	FAIR	POOR
V10	Roof	<u>GOOD</u>	FAIR	POOR
V28	Firetube	<u>GOOD</u>	FAIR	POOR


Light Surface Scale/Rust.
Scale Buildup.

INTERNAL GOOD BOWED OVALLED
FLANGE LEAKING: YES NO

V8	Nozzles	<u>GOOD</u>	FAIR	POOR
V7	Welds	<u>GOOD</u>	FAIR	POOR
V21	Anodes	GOOD	FAIR	POOR
V27	Coating	GOOD	FAIR	POOR

Internal Buildup Loose Rust
BACKWELDING REQ'D: YES NO

N/A
TYPE: N/A



Notes & Summary of Recommendations:

Icy Patches Cover Some Areas
of Floor Due to Steam Cleaning.

Surface Scale/Rust on Shell and
Floor.

Tank in Good Overall Condition

Tank To be moved/Relocated.

Approvals
Inspector
Husky Inspector

Name
Stephen Bryan, IRIS NDT

Inspection
Interval: 5 yr

Entered in RBMI: ☒

Signature
Stephen Bryan

Date
Jan 10, 14
JAN 17 2014