66150922 Page 2012. 🙆 Husky Energy Equipment #: Area: Cost Centre: Tank Inspection Report 4091091 Dee Neison Approver #: 22-2000 425 WO#: Approver: 8400749718 Requisitioned By: Rober SKOLTOOD Location: 103/8-30-48-1W4 PO# Universal 17105-2 Tank Type: HEAVY Dil Storage. Manufacturer: Serial #: Shell /4 3/16 Floor 1/4 Year Built: Thickness: 1000 661 Capacity: **External Inspection** T61 Insulation GOOD FAIR POOR T64 Cladding GOOD FAIR POOR T32 Base / Landscaping GOOD FAIR POOR ENDARIAMES T14 Liner / Containment GOOD FAIR POOR In Containment Ground Cable YESNO **T8** Ladder/ Stairway GOOD FAIR POOR **T6** GOOD FAIR POOR **T7** Platform T41 Piping Alignment GOOD FAIR POOR GOOD FAIR POOR T15 Shell (YES NO T44 Envirovault SOOD GOOD FAIR POOR T16 Roof GOOD FAIR POOR T11 Paint Internal Inspection GOOD FAIR POOR Light Surface Scale/Rust T11 Floor GOOD FAIR **POOR** V9 Shell V10 Roof GOOD FAIR POOR GOOD FAIR POOR INTERNAL GOOD BOWED OVALLED V28 Firetube FLANGE LEAKING: YES NO GOOD FAIR POOR PIGEON FECES BUILDUP TOTERNALLY. V8 Nozzles V7 Welds V21 Anodes GOOD FAIR POOR GOOD FAIR POOR V27 Coating TYPE: Notes & Summary of Recommendations: Icy Patches Cover on Some Areas of FLOOR From Stam Cleaning. 588 Pibeon teres Buildup on Vayet AND Internal Piping, Firetube Surface Scale on From Ano Shell. TANK IN GOOD OVERALL Consition. TANK To be moved/Relocated Inspection Interval: Entered in RBMIs Z Approvals Date OTEPHEN BRYAN, IRIS NOT Inspector AN 10.14 Husky Inspector IAN 1 7 2014 Page 1 of 1