46179309



## **MAGNETIC PARTICLE INSPECTION REPORT**

MT-165828-03

Page 1 of 1

Procedures: MT 2V, PROC 5.0	Job / P.O. #: SEE BELOW	IRISNDT #: 165828	Date: 23-Jan-13
Code: API-650 SEC. 8.2.4.	Client: HUSKY OPERATIONS		
	Location: 5-27-48-2W	4M	
	Item Inspected: TANK UPG	RADES	
Surface Condition: Painted ☐ Sandblasted ☐ Machined ☐ As Cast ☐ As Forged ☐ Weldment ☒ Other ☐			
Material: P1		Thickness: N/A Heat T	reatment: AS WELDED
Magnetizing Equipment: Yoke ⊠ Coil	☐ Prod ☐ Bench: Hea	adshot Central Conductor Coi	il 🗌
IRISNDT #: 40137 Mfg: CONTOUR PROBE Calibration Date: 30-Oct-12			
Blacklight:   IRISNDT #: Verification per ASM	Mfg: E V Art 7 T.777.2	Calibration Date	te: -Jan-10
Whitelight: Battery Powered Min. 110V Power Min. 60V	_ }	Held within 30 cm (12in) of the inspection provides minimum 1000 Lx (100fc)	ı surface
Method of Magnetization: AC $\boxtimes$ DC $\square$	Continuous  Residual		
Magnetic Particles: Dry ☐ Wet ⊠	Red ☐ G	rey Black Fluorescent	
Batch #: 301-12	Mfg: MAGNA	AFLUX Type: 7C	
Background: ⊠ Batch #: 1094	Mfg: ARDRO	X Type: 8901W	
A MAGNETIC PARTICLE EXAMINATION WAS CARRIED OUT, AS REQUESTED, ON THE FOLLOWING ITEMS:  TANK#1 SN#023378-10  1-4"H20 EQUALIZER NOZZLE AND REPAD  1-8"OIL RISER NOZZLE AND REPAD  1-8"OIL RISER NOZZLE AND REPAD  1-3'H20 EQUALIZER NOZZLE AND REPAD  1-8"OIL RISER NOZZLE AND REPAD  1-8"OIL R			
Unit#: 330   Kilometers: 0	Consumables:	Interpretation by: RANDY TRADEWELL  (Print)  Compared to the content of the conte	SNT-TC-1A 2 - C.G.S.B. 2 (Level) C.G.S.B.# 5357
5311 - 86 Street Edmonton, Alberta, T6E 5T8 Phone: (780) 437-2022 Fax: (7 Calgary (403) 279-6121	(0) 438-1436 Cold Lake (780) 594-11	14 Corous Christi	TX (361) 888-4700

(780) 875-6455 (780) 674-3018 (780) 955-7616

Fort McMurray High Level Red Deer Medicine Hat

(780) 594-1114 (780) 743-1536 (780) 956-4094 (403) 347-1742 (403) 427-6284

Corpus Christi, TX Deer Park, TX Matrix,Houston, TX Texas City, TX Tulsa, OK

(361) 888-4700 (281) 476-4444 (713) 722-7177 (490) 945-2262 (918) 446-8773