66169971



## MAGNETIC PARTICLE INSPECTION REPORT

CA1091-MT-46

Page 1 of 1

Procedure: 5.0
Technique: MT-2V

Rev: 2.0

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873 Calgary (403) 279-6121 Cold Lake

(780) 875-6455

(780) 674-3018

(780) 955-7616

Lloydminster

Barrhead

Nisku

Client: HUSKY OIL OPERATIONS

IRISNDT #: LYN18000148

Date: 06-Feb-18 WO #: 50053398

Code / Standard: API 650 - Sect 8.2	.4 Locatio	n: 8-20-49-2W4M		PO #: 8401226309	
Other: N/A		Item Inspected: Double tank upgrades		1 0 W. 0401220303	
Surface Condition: Buffed	Material: Carbon St		Thickness: > 3/16"	Heat Treatment: Not Applic	able
Magnetizing Equipment: Yoke	Method of Magnetiz	zation: AC Continuous	IRISNDT #: 40099	Mfg: Contour probe	abie
Verification Date: 06-Feb-18		∷ ⊠ 10 lb. □ 40 lb.	Serial #: 49037	Verification per ASME V Ar	+ 7 T 76'
Blacklight: ☐ Y ⊠ N/A	IRISNDT#:		Blacklight Meter:	IRISNDT #:	17 1.702
	Verification per ASM	Verification per ASME V Art 7 T.777.2		Calibration Due Date:	
Whitelight: ⊠ Y ☐ N/A	Verification per ASM		Lighting Equipment:	Yoke Light	
Magnetic Particles:	☐ Dry ☒ Wet			Black  Fluorescent	
	Batch #: 1539	Mfg: Ardrox	Type: 8		
Background: ⊠ Y □ N/A	Batch #: 1608	Mfg: Ardrox	Type: 8		
		Appr: Yvon Pilon 2Z-			
		1-8"Oil X-o 1-4"X-sting Welder ID:	equalizer nozzle and repover nozzle and repad g nozzle and repad : JH results: Acceptable to 0		•
nspection Limitation(s): N/A  Unit#: 1039 Kilometers:	0 Consumables:		Interpretation by:		
In: Out: Hrs:	Min		Tristan Somn	at .	
In: Out: Hrs:			2 A	C.G.S.B.:	(Level)
Personnel:			(Sign)	C.G.S.B #:	7829
Fristan Sommerfeld Iordan Ross			Client Representative:	)	
			I am in full agreement with report contents		

(780) 826-6105

(780) 743-1536

(403) 347-1742

Fort McMurray

Red Deer

(403) 217-9684

(780) 437-2022

Engineering, Calgary

Engineering, Edmonton