

MAGNETIC PARTICLE INSPECTION REPORT

CA1213-MT3-85

Page 1 of 1

Procedure: 5.0 Technique: MT-2V

Code/Standard: API 650 - Sect 8.2.4

Rev: 3.0

Client: HUSKY OIL OPERATIONS LIMITED

IRISNDT #: LYN1901614 Location: 11-14-49-02w4 Date: 2019-Sep-27 WO #: 81422566

PO #: 8401382216

Other:	Item Inspected: Tank #2 items		APPR#	2Z-2001456
Requested By: Arnie Domes Approver: Jay Sinclair				
Specification: Standard:				
Surface Condition: As Welded Material:	P1	Thickness: >1/8"	Heat Treatment: N	ot Applicable
Magnetizing Equipment: Yoke Method o	Magnetization: AC Continuous	Asset #: 40385	Mfg: Contour Prob	е
Verification Date: 2019-Sep-27 Verification	on Weight: 🛛 10 lb. 🗌 40 lb.	Asset #: 40490	Verification per ASM	ME V Art 7 T-762
Magnetic Particles: Dry ☐ Wet ☒	Red ☐ Grey ☐ Black ☒	Fluorescent		
Batch #: 65100617	Manufacture: ARDROX		Type: 8032	
⊠Background				
Batch #: 65110817	Manufacture: ARDROX		Type: 8901W	
☐ Blacklight (N/A)				
Asset #:	Blacklight r	meter: Asset #:	Cal Due Da	te:
⊠Whitelight				
Lighting Equipment: Yoke Light (10W)	Verification per ASME V Art 7 T-7	777.1		
Inspection Scope: To perform a wet black on white magnetic particle inspection on the following tank items				
Results: No indications noted. Acceptable to code			ting nozzle	
Inspection Limitation(s): N/A				
Unit#: Kilometers: Consum	ables:	Interpretation by:	200	
In: Out: Hrs: Min		Logan Skinn		1A: <u>2</u> 3.B.: 2
In: Out: Hrs:		I Mh.		(Level)
Personnel:		(Sign)	C.G.S.	B #:17159
Logan Skinner		Client Representative:		
Brayden McGinnis		(Print)	
		with report contents (Sign)		
5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747	Fox (790) 429 4972	(Sign)		

(780) 826-6105

(780) 743-1536

(403) 347-1742

www.irisndt.com

Fort McMurray

Red Deer

(403) 279-6121

(780) 875-6455

(780) 674-3018

(780) 955-7616

Calgary

Lloydminster

Barrhead

Nisku

(403) 217-9684

(780) 437-2022

(780) 437-2022

Engineering, Calgary

Engineering, Edmonton

Rope Access Services

Offices also located in USA and UK