

MAGNETIC PARTICLE INSPECTION REPORT

CA0135-MT-27 Page 1 of 1

66155561

Procedure: 5.0 Rev 1 Technique: MT-2V Code: API 650 - Sect 8.2.4 Other:	Client: HOPS Date: 11-Jun-14 IRISNDT #: 169584 WO #: 4094529 Location: 16-1-45-1-W4M PO #: 8400817115 Item Inspected: 1-TANK
PRODUCTION OF THE PRODUCTION O	
Control of the Contro	
Material: P1	Thickness: VARIOUS Heat Treatment: N/A
Magnetizing Equipment: Yoke ⊠ Coil ☐ Permanent	
Method of Magnetization: AC ☑ DC ☐ Continuous	
Blacklight: Y N/A IRISNDT #: Blacklight Meter: IRISNDT #: Calibration Date:	
Whitelight: Y ⊠ N/A ☐ Verification per ASME V Art 7 T	
Magnetic Particles: Dry ☐ Wet ☑ Batch #: 1259-56	Red ☐ Grey ☐ Black ☑ Fluorescent ☐ Mfg: MAGNAFLUX Type: 7C
Background: ⊠ Batch #: 1321	Mfg: ARDROX Type: 8901W
1-3" SCADA NOZZLE AND REPAD 1-4" STINGER NOZZLE AND REPAD 3-PATCHES 2-3/4" NIPPLES 4-SUPPORT PADS 1-TAILING LUG REQ: ROB @ PIPEMASTER APPR: RICK FOUNTAIN 2Z-0290577 RESULTS: WELDS ACCEPTABLE TO CODE.	
Inspection Limitation(s):	Interpretation by:
Unit#: 565 Kilometers: 55 MIN.	BERNARD MICNALTY SNT-TC-1A: II
In: 1230 Out: 1400 Hrs: 1.5 In: Out: Hrs: 2-H2S GAS	MONITORS (Print) Bernard Whelty C.G.S.B.: (Level) C.G.S.B.: 5494
Personnel: BERNARD: McNALTY	(Signature) Client Representative: (Print)
STEPHEN WOOLFREY	I am in full agreement with report contents (Sign) Kay Mullim

5311-96 Steet, Edmonton, Alberta. T6E 5T8 Phone: (780) 437-2022 fax: (780) 436-4873 Calgary (403) 279-6121 Cold Lake Lloydminster (780) 875-6455 Fort McMurray Red Deer Nisku (780) 955-7616

(780) 826-6105 (780) 743-1536 (403) 347-1742

Engineering, Calgary (403)
Engineering, Edmonton (780)
Rope Access Services (780)
Offices also located in USA and UK

(403) 217-9684 (780) 437-2022 (780) 437-2022