



**MAGNETIC PARTICLE  
INSPECTION REPORT**
**CA1213-MT-148**

Page 1 of 2

<b>Procedure:</b> 5.0 <b>Technique:</b> MT-2V <b>Code/Standard:</b> API 650 - Sect 8.2.4 <b>Other:</b>	<b>Rev:</b> 3.0 <b>Client:</b> HUSKY OIL OPERATIONS LIMITED <b>IRISNDT #:</b> LYN1801819 <b>Location:</b> 100/10-24-49-03W4 <b>Item Inspected:</b> Tank #1 Production	<b>Date:</b> 14-Nov-18 <b>WO #:</b> 50061964 <b>PO #:</b> 8401226309 <b>APPR#</b> 2Z-2000425
---	---	---

<b>Surface Condition:</b> As Welded	<b>Material:</b> Carbon Steel	<b>Thickness:</b> >3/16"	<b>Heat Treatment:</b> Not Applicable
<b>Magnetizing Equipment:</b> Yoke	<b>Method of Magnetization:</b> AC Continuous	<b>IRISNDT #:</b> 40118	<b>Mfg:</b> Contour Probe
<b>Verification Date:</b> 14-Nov-18	<b>Verification Weight:</b> <input checked="" type="checkbox"/> 10 lb. <input type="checkbox"/> 40 lb.	<b>Serial #:</b> 40490	<b>Verification per ASME V Art 7 T-762</b>
<b>Blacklight:</b> <input type="checkbox"/> Y <input checked="" type="checkbox"/> N/A	<b>IRISNDT #:</b>	<b>Blacklight Meter:</b>	<b>IRISNDT #:</b>
	<b>Verification per ASME V Art 7 T-777.2</b>		<b>Calibration Due Date:</b>
<b>Whitelight:</b> <input checked="" type="checkbox"/> Y <input type="checkbox"/> N/A	<b>Verification per ASME V Art 7 T-777.1</b>	<b>Lighting Equipment:</b> Yoke Light (10W)	
<b>Magnetic Particles:</b>	<input type="checkbox"/> Dry <input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Red <input type="checkbox"/> Grey <input checked="" type="checkbox"/> Black <input type="checkbox"/> Fluorescent	
	<b>Batch #:</b> 1539	<b>Mfg:</b> ARDROX	<b>Type:</b> 8032
<b>Background:</b> <input type="checkbox"/> Y <input type="checkbox"/> N/A	<b>Batch #:</b> 65110817	<b>Mfg:</b> ARDROX	<b>Type:</b> 8901W

Wet Black MPI was carried out as requested on the following tank items as listed



Results: No Indications noted. Acceptable to code.


**Inspection Limitation(s):** none

<b>Unit#:</b> 667 <b>In:</b> _____ <b>Out:</b> _____ <b>Hrs:</b> _____ <b>In:</b> _____ <b>Out:</b> _____ <b>Hrs:</b> _____ <b>Personnel:</b> Logan Skinner	<b>Consumables:</b> Min Requested By: Mike Ross Approver: Dee Nelson	<b>Interpretation by:</b> <b>Logan Skinner</b> (Print) (Sign) _____ Client Representative: I am in full agreement with report contents (Print) _____ (Sign) _____	<b>SNT-TC-1A:</b> 2 <b>C.G.S.B.:</b> 2 (Level) <b>C.G.S.B #:</b> 17159
---	---	--	--

 5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873  
 Calgary (403) 279-6121 Cold Lake (780) 826-6105  
 Lloydminster (780) 875-6455 Fort McMurray (780) 743-1536  
 Barrhead (780) 674-3018 Red Deer (403) 347-1742  
 Nisku (780) 955-7616 www.irisndt.com

 Engineering, Calgary (403) 217-9684  
 Engineering, Edmonton (780) 437-2022  
 Rope Access Services (780) 437-2022  
 Offices also located in USA and UK





8" Nozzle & repad



4" Nozzle & Repad



8" Backweld



4" Backweld

IRISNDT #: LYN1801819

Date: 14-Nov-18

Logan Skinner

(Print)

(Sign)

Client: HUSKY OIL OPERATIONS LIMITED

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873  
 Calgary (403) 279-6121 Cold Lake (780) 826-6105  
 Lloydminster (780) 875-6455 Fort McMurray (780) 743-1536  
 Barrhead (780) 674-3018 Red Deer (403) 347-1742  
 Nisku (780) 955-7616 www.irisndt.com

Engineering, Calgary (403) 217-9684  
 Engineering, Edmonton (780) 437-2022  
 Rope Access Services (780) 437-2022  
 Offices also located in USA and UK