

Equipment #:

Area:

Cost Centre:

66143095
AS-Edgerton
1 Dina

Page 2 of 2



Tank Inspection Report

Approver:

Dee Nelson

Approver #:

22-2000425

WO#:

4094154

Requisitioned By:

Roger Skirflood

Location:

100/15-1-45-1 W4

PO#

8400800876

Manufacturer:

Universal

Serial #:

15282-21

Tank Type:

Heavy oil Storage

Capacity:

1000 bbl

Thickness:

Floor 1/4" Shell 1/4" 3/16"

Year Built:

2008

External Inspection

T61	Insulation	<u>GOOD</u>	FAIR	POOR
T64	Cladding	<u>GOOD</u>	FAIR	POOR
T32	Base / Landscaping	<u>GOOD</u>	FAIR	POOR
T14	Liner / Containment	<u>GOOD</u>	FAIR	POOR
T8	Ground Cable	<u>YES</u>	NO	
T6	Ladder/ Stairway	<u>GOOD</u>	FAIR	POOR
T7	Platform	<u>GOOD</u>	FAIR	POOR
T41	Piping Alignment	<u>GOOD</u>	FAIR	POOR
T15	Shell	<u>GOOD</u>	FAIR	POOR
T44	Envirovault	<u>YES</u>	NO	
T16	Roof	<u>GOOD</u>	FAIR	POOR
T11	Paint	<u>GOOD</u>	FAIR	POOR

N/A

on PLANKS To be Relocated
In Containment

N/A Disconnected

ENTERED
June 23/14

N/A

Internal Inspection

T11	Floor	<u>GOOD</u>	FAIR	POOR
V9	Shell	<u>GOOD</u>	FAIR	POOR
V10	Roof	<u>GOOD</u>	FAIR	POOR
V28	Firetube	<u>GOOD</u>	FAIR	POOR

Light Scale/Rust

Light Scale/Rusty Surface.

INTERNAL: GOOD BOWED OVALLED
FLANGE LEAKING: YES NO

V8 Nozzles

GOOD FAIR POOR

V7 Welds

GOOD FAIR POORBACKWELDING REQ'D: YES NO

V21 Anodes

GOOD FAIR POOR

V27 Coating

GOOD FAIR POOR

TYPE:

N/A
N/A

Notes & Summary of Recommendations:

Floor is Covered in Rust Scale, UT Readings suggest tank in Good overall condition. For 5 YR Turnaround.

Nozzles Have oil and Buildup on the Internal Surface but are Sch 80's.

Inspection Interval:

5 yr

Entered in RBMI: ☒

Signature

Approvals

Inspector

Husky Inspector

Name
STEPHEN BYAN IRIS NDTDate
May 28, 2014
JUN 20 2014