

66130261

IRIS NDT

NONDESTRUCTIVE INSPECTION REPORT

CA1098-NDT-65

Page 1 of 1

Type of Inspection: VT Rev: 2.0

Client: HUSKY OIL OPERATIONS

Date: 05-Feb-18

Test Technique: UT thickness(4.2)

IRISNDT #: LYN1800139

WO #: 50053398

Equipment: DMS2 / FLASHLIGHT GRINDER

Location: 100 /8-20-49-2 w4

PO #: 8401226309

Code / Standard: client information

Item Inspected: 1000bbl tank s/n# 07-159-4

traveled to location to inspect tank, tank was not steamed and could not be inspected.



approver: yvon pilon 2Z-2007533

Inspection Limitation(s): no inspection carried out.

Unit#: 767	Kilometers: 0	Consumables:	Interpretation by:
In: _____ Out: _____ Hrs: _____		MIN	Stephen Bryan
In: _____ Out: _____ Hrs: _____			(Print) _____
Personnel:			(Sign) _____
STEPHEN BRYAN / BRAYDEN MCGINNIS			Client Representative: _____
			(Print) _____
			I am in full agreement with report contents
			(Sign) _____

5311 - 86 Street NW, Edmonton, Alberta T6E 5T8 Phone (780) 437-4747 Fax (780) 436-4873
 Calgary (403) 279-6121 Cold Lake (780) 826-6105
 Lloydminster (780) 875-6455 Fort McMurray (780) 743-1536
 Barrhead (780) 674-3018 Red Deer (403) 347-1742
 Nisku (780) 955-7616

www.irisndt.com

Engineering, Calgary (403) 217-9684
 Engineering, Edmonton (780) 437-2022
 Rope Access Services (780) 437-2022
 Offices also located in USA and UK

IRISNDT-CA-E-2015E